

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT						
	INCOME INSURAN	ICE LTD		Ref:	CS/INC24090047/Avh3e2(N)	
	75 BRAS BASAH FINCOME CENTRES		Date:	21/01/2025		
	ATTN: HELENA TA	۱N		Code:	INC	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SMY 8552K	Veh. Inspecte	d	SLA 3548U	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	MT/1293403-002	Excess (\$)		0.00	
	Assign From	HELENA TAN	Assign Date		03/09/2024	
2. Vehicle Particulars & Condition						
	Make & Model	MAZDA 5	c.c		1998	
	Engine No.	HIDDEN	Year of Reg.		2016	
	Chassis No.	JM6CW1071G0123309	Colour		GREY	
	Odometer	173634 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	195/55 R16	MICHELIN		6 mm	
	L/H Front Tyre	195/55 R16	MICHELIN		6 mm	
	R/H Rear Tyre	195/55 R16	MICHELIN		6 mm	
	L/H Rear Tyre	195/55 R16	MICHELIN		6 mm	
4. Description of Damages						
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
	DAMAGES SEE DETAILS.					
					8 **	
5. General Information						
	Accident Date	02/09/2024	Inspect Date /	Time	04/09/2024 (01:28 PM)	
	Survey held at	HD PERFECT AUTOWORK PTE LTD				
	8 KAKI BUKIT AVENUE 4, #08-09, PREMIER @ KAKI BUKIT, SINGAPORE 415875					
5a.	5a. Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	5b. Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days					