

TP Budget Direct
Veron

VEHICLE REPAIR ESTIMATE

Make/ Model : MITSUBISHI ATTRAGE Date: 03.09.2024
Chassis No : MMBSTA13AHH003652 Vehicle No: SLK8760L
Date/Time of Accide 02092024//0817HRS DATE OF REG : 03.02.2017

Materials Cost/ Spare Parts Cost

TO BE COMPLETED BY SERVICE ADVISOR

ITEMS	PARTS DESCRIPTION	QTY	LIST PRICE \$	FINAL PRICE \$
1	BOOTLID <i>Dented</i>	1	\$ 960.70	\$ 960.70 <i>890</i>
2	BOOTLID HINGES <i>new</i>	2	\$ 98.70	\$ 197.40 <i>+</i>
3	BOOTLID "ATTRAGE" EMBLEM	1	\$ 85.60	\$ 85.60 <i>✓</i>
4	BOOTLID "MIVEC" EMBLEM	1	\$ 87.20	\$ 87.20 <i>✓</i>
5	BOOTLID "CC" EMBLEM	1	\$ 92.30	\$ 92.30 <i>✓</i>
6	BOOTLID HINGES <i>new</i>	2	\$ 98.60	\$ 197.20 <i>+</i>
7	BOOTLID STOPPER	2	\$ 30.00	\$ 60.00 <i>+</i>
8	BOOTLID CHROME MOLDING	1	\$ 345.60	\$ 345.60 <i>+</i>
9	BOOTLID NUMBER PLATE LAMPS	2	\$ 69.80	\$ 139.60 <i>+</i>
10	BOOTLID INNER LOCK	1	\$ 223.50	\$ 223.50 <i>✓</i>
11	BOOTLID LOCK CATCH	1	\$ 46.80	\$ 46.80 <i>+</i>
12	BOOTLID INNER TRIM	1	\$ 298.90	\$ 298.90 <i>+</i>
13	BOOTLID WEATHERSTRIP	1	\$ 195.80	\$ 195.80 <i>+</i>
14	BOOTLID OUTER LOCK SWITCH	1	\$ 246.60	\$ 246.60 <i>+</i>
15	REAR BUMPER	1	\$ 798.00	\$ 798.00 <i>✓</i>
16	REAR BUMPER RETAINER	2	\$ 85.60	\$ 171.20 <i>+</i>
17	REAR BUMPER REFLECTORS	2	\$ 78.50	\$ 157.00 <i>+</i>
18	TAILAMPS	2	\$ 445.90	\$ 891.80 <i>485.50</i>
19	TAILAMPS INNER SEAL	2	\$ 35.00	\$ 70.00 <i>+</i>
20	TAILAMPS PANELS	2	\$ 235.60	\$ 471.20 <i>+</i>
21	END PANEL <i>Dented</i>	1	\$ 639.50	\$ 639.50 <i>483</i>
22	END PANEL TOP GARNISH	1	\$ 178.30	\$ 178.30 <i>✓</i>
23	SPARE TYRE PANEL	1	\$ 986.30	\$ 986.30 <i>+</i>
24	SPARE TYRE TOP BOARD	1	\$ 192.50	\$ 192.50 <i>✓</i>
25	SPARE TYRE WHEEL NUT	1	\$ 46.00	\$ 46.00 <i>+</i>
26	REAR AIR VENT	1	\$ 52.30	\$ 52.30 <i>+</i>
27	REAR AIR VENT OUTER GARNISH	1	\$ 65.20	\$ 65.20 <i>+</i>
28	REAR FENDER INNER COWLINGS	2	\$ 245.80	\$ 491.60 <i>+</i>
29	REAR WINDSCREEN INNER SEAL	1	\$ 50.00	\$ 50.00 <i>+</i>
Total List Price Cost				\$ 8,438.10
				\$ 7,594.29

3515.40
23163.86

SPECIAL NETT	PARTS DESCRIPTION	QTY	PRICE \$	FINAL PRICE \$
1	REAR BUMPER CLIPS <i>new</i>	1 SET	\$ 30.00	\$ 30.00 <i>✓</i>
2	REAR FENDER INNER COWLING CLIPS	2 SET	\$ 30.00	\$ 60.00 <i>+</i>
3	REAR FENDER INNER TRIMS CLIPS	2 SET	\$ 60.00	\$ 120.00 <i>+</i>

4	END PANEL SEALANT <i>new</i>	2	\$ 80.00	\$ 80.00	<i>60</i>
5	SPARE TYRE FLOOR INSULATOR PADS <i>nt</i>	1 SET	\$ 150.00	\$ 150.00	<i>+</i>
6	WINSCREEN SEALANT <i>new</i>	1 SET	\$ 80.00	\$ 80.00	<i>+</i>
7	REVERSE SENSORS <i>Don't</i>	1 SET	\$ 250.00	\$ 250.00	<i>2w</i>
8	REAR NUMBER PLATE WITH CASING <i>nt</i>	1 SET	\$ 50.00	\$ 50.00	<i>+</i>
Total Special Nett Items				\$ 730.00	
Labour Works/ Panel Beating Related Works					
Job Scope				Quotation	
TO RENEW DAMAGED PARTS, REPLACE, BEAT, WELD, REALIGN AND ALIGNE ALL PARTS				\$ 1,800.00	
Spray Painting					
Job Scope				Quotation	
TO RESPRAY AFFECTED AREAS				\$ 1,600.00	
Others Cost (Accident Repair Related Expenses)					
Job Scope				Quotation	
TO TUFFCOAT AFFECTED AREA				\$ 200.00	<i>80</i>
TO REMOVE/ REFIT /REPLACE REAR BOOTLID MECHANISM				\$ 120.00	<i>80</i>
TO REMOVE/ REFIT REAR INTERIOR UPHOLSTERY				\$ 150.00	<i>80</i>
TO CONDUCT CHECK ON TAILAMPS WIRING				\$ 120.00	<i>30</i>
TO REMOVE/ REFIT REAR SENSOR AND DISTANCE SETTLING				\$ 150.00	<i>50</i>
TO REMOVE/ REFIT REAR WINDSCREEN FOR FENDER REPLACEMENT				\$ 150.00	<i>+</i>
LABOUR TO APPLY SEALANT ON THE AFFECTED AREA				\$ 180.00	<i>+</i>
Total Others Cost				\$ 1,070.00	
GRAND TOTAL				\$ 12,794.29	

Person Incharge: JOHN
Direct Contact: 98287487
Email: ktmotorwerk@hotmail.com

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adnan Lj
F/S 04/09/24
06hys

Supplementary: 257.40.
total 5631.26
L/S : 4.51c
4.51c

REQUEST FOR SUPPLEMENTS PARTS

Vehicle No	SLK8760L	Date of Request	04.09.2024
Vehicle Model	MIT ATTRAGE	Number of Days to Extend (If any)	
S/N	PART DESCRIPTION		LIST PRICE
1	KEYLESS ENTRY ANTENNA (841MB8637A526)	<i>Antena</i> 166	\$321.70
2	BUZZLE KEYLESS MODULE (8637B366)	<i>Antena</i> 120	\$487.50
3	TO PROGRAME AND CODE MODULE KEYLESS		\$250.00 <i>X</i>

Supplementary: 286
 257.40