

**AUTOBACS CAR CARE (SINGAPORE) PTE. LTD.**

8 Kaki Bukit Ave 4 #08-40/45/46 Premier@Kaki Bukit S(415875)
Tel : 6702 1555 Fax : 6702 1444
Co. Reg No. : 201500047H GST No. : 201500047H
Email : st.sim@autobacs.com.sg

TO	: LIBERTY INSURANCE (SLH8784J)	DATE	: 2-Sep-24
ATTENTION	: MOTOR CLAIMS DEPARTMENT	JOB TYPE	: T/P CLAIMS
OWNER PARTICULAR			
OWNER ID	: SXXXX000Z	P -	_____
		S -	_____
		L -	_____
VEHICLE DETAILS			
VEHICLE NO.	: SLF6241H	TOTAL :	_____
MODEL / MAKE	: TOYOTA COROLLA ALTIS	L/S -20% :	_____
CHASSIS NO.	: MR053REH104549956	SUB TOTAL :	_____
ACCIDENT DETAIL			
DATE	: 2-Sep-24		
TIME	: 09:00 HRS	CONTACT PERSON	: MR. SIM 9844 0974

QUOTATION SUMMARY PAGE 01**CLAIMS DETAIL : PARTS LIST**

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	Rear bumper	1	\$ 780.00	\$ 780.00
2	Rear end panel	1	\$ 913.00	\$ 913.00
TOTAL PRICE				\$ 1,693.00
LESS -25%				\$ (423.25)
SUB TOTAL PRICE				<u>\$ 1,269.75</u>

QUOTATION SUMMARY PAGE 02**CLAIMS DETAIL : LABOUR CHARGES AND SPRAY PAINTING**

TO LABOUR CHARGE FOR REMOVING REAR BUMPER AND END PANEL OUT TO FACILITATE REPLACEMENT OF DAMAGED PART	\$ 500.00	200	
TO RESPRAY REAR BUMPER AND END PANEL	\$ 500.00	400	

TOTAL \$ 1,000.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 1,269.75
TOTAL LABOUR COST : \$ 1,000.00
TOTAL REPAIR COST : \$ 2,269.75

APPROVED DETAILS

NO. OF REPAIR DAYS
REPAIR UNDER

LKK Auto Consultants hereby notify the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

DAYS

OR LUMP SUM

not Authorized
Mr. S
4/9/24
7/2 \$ 600
2 days