

TP Libby.

XiaoChun 10 Sep 2024

GBG 4435 S TOYOTA DYNA

No	Qty	Parts Description	Estimated Parts Price
1	1	Rear tailboard lower panel <i>pipe</i>	\$ 878.50 <i>X</i>
2	2	Rear taillamps <i>RH ut</i>	\$ 659.30 <i>245</i>
3	2	Rear taillamp panels <i>new</i>	\$ 399.00 <i>X</i>
4	1	Rear number plate panel <i>best</i>	\$ 98.50 <i>✓</i>
5	2	Rear number plate lamps	\$ 179.30 <i>X</i>
6	1	Rear exhaust pipe <i>new</i>	\$ 752.60 <i>X</i>
7	1	Rear exhaust mounting <i>new</i>	\$ 48.90 <i>X</i>
			\$ 3,016.10
		less 25%	\$ 754.03
			\$ 2,262.08

343.50

257.62

No	Qty	Parts Description	Estimated Parts Price
		<u>Special Nett Items</u>	
1	1	Rear tailboard "12 PAX" sticker <i>new</i>	\$ 25.00 <i>15</i>
2	1	Rear tailboard "70KM/H" sticker <i>new</i>	\$ 25.00 <i>X</i>
3	1	Rear number plate <i>best</i>	\$ 50.00 <i>30</i>
4	1	Rear reverse sensor (1 set) <i>new</i>	\$ 280.00 <i>X</i>
5	1	Rear tailboard -LH <i>new</i>	\$ 1,800.00 <i>X</i>
6	1	Rear tailboard -RH <i>Dented</i>	\$ 1,800.00 <i>1200</i>
7	2	Rear tailboard lock bars <i>broken</i>	\$ 960.00 <i>300</i>
8	2	Rear tailboard lock bar strikers <i>new</i>	\$ 230.00 <i>X</i>
9	2	Rear tailboard lower hinges <i>new</i>	\$ 290.00 <i>X</i>
			\$ 5,460.00

1545

Total parts : \$ 7,722.08

No	Description	Labour Charges
1	To remove, refit, replaced damaged lamps and check up rear electrical wiring	\$ 80.00 30
2	To remove and refit rear reverse sensor.	\$ 150.00 50
3	To apply undercoating on repaired and replaced panel.	\$ 150.00 X.
4	To provide labour charges, workmanship to dismantle above damaged parts, repair including cut and weld ; re-align body structure and damaged consistent to the accident.	\$ 1,800.00 400. 880
5	To respray painting include polishing and waxing on the changed body parts, repaired portions where consistent to the accident.	\$ 1,600.00 400.
Total labour :		\$ 3,780.00

Total parts :	\$ 7,722.08
Total labour :	\$ 3,780.00
Total repair cost :	\$ 11,502.08

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Admin Lj
H/S 10/09/24.

04 Days.

Total 2682.62

L/S: 2.11K