

**Note: This document has not been finalised.****LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Khong Lin Hui Lynn

Date: 05 Sep 2024

**Preliminary Advice**

Vehicle No	: SLH144J	Accident Date	: 03/09/2024
Make	: BMW 216D	Policy No.	: DMHCSNW00021922302
Assignment Date	: 04/09/2024	Excess	: S\$1,250.00
Date of Inspection	: 04/09/2024	Est. Duration of Repair	: 0
Inspection At	: DING AUTO PTE LTD (CARROS CENTRE) 60 JALAN LAM HUAT, #06-46/47 CARROS CENTRE SINGAPORE 737869		

**Point of Impact / General Description of Damages**

Pending investigation.

Repairer's Estimate (Gross)	:S\$	Total loss
Revised Amount	:S\$	Total loss
Check Items (Estimated)	:S\$	0.00
Total	:S\$	0.00

Lump Sum Repair	:S\$
-----------------	------

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	42,000.00
COE / PARF Rebate	:S\$	26,003.00
Salvage Value	:S\$	
Margin for Repair	:S\$	15,997.00

**Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( x ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( x ) Other comments : Pending investigation.