



PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation


From :	Customer :
PEGASUS ENGINEERING & TRADING PTE LTD 74 KIAN TECK ROAD SINGAPORE 628800 Officer in Charge : VIVIAN TAN EE WI Tel : Email :	GRAB RENTALS PTE LTD 3 MEDIA CLOSE #07-03 SINGAPORE 138498 Attn : Tel : Fax No. :

Quotation No. : QO24/09-1041	Quotation Date : 05/09/2024	Terms : 60 DAYS
Vehicle No. : SNR5609B	Chassis No. : KMHLN41JVRU112784	Policy Number :
Model : CN7 AVANTE 1.6 Petrol-Electric		Date of Accident : 01/09/2024
Third Party Insurer : SMRT		TP Vehicle No. : SMB5056S
Remarks :		

ITEM	DESCRIPTION	Qty	UNIT PRICE	AMOUNT (SGD)
1	FRONT BUMPER	1	850.0000	850.00 ✓
2	FRONT BUMPER SIDE RETAINER (LHS)	1 ✗	68.0000	68.00
3	FRONT BUMPER CLIPS @ 10PCS	10	4.0000	40.00 ✓
4	FRONT BUMPER "H" LOGO	1	74.0000	74.00
5	FRONT BUMPER FOGLAMP COVER (LHS)	1	58.0000	58.00
6	FRONT BUMPER FOGALMP (LHS)	1	220.0000	220.00
7	FRONT BUMPER SIDE MOULDING PIECE (LHS) (BLACK COLOUR)	1	35.0000	35.00 ✓
8	FRONT BUMPER SIDE MOULDING (LHS) (MATT COLOUR)	1	242.0000	242.00 ✓
9	FRONT BUMPER SIDE AIR DUCT (LHS)	1	40.0000	40.00
10	FRONT FENDER (LHS)	1	1,397.0000	1,397.00 ✓
11	FRONT FENDER SPLASH SHIELD (LHS)	1	127.0000	127.00
12	FRONT FENDER SPLASH SHIELD CLIPS @ 10PCS	10	4.0000	40.00
13	FRONT SPORT RIM (LHS)	1	1,237.0000	1,237.00 ✓
14	FRONT HEADLAMP (LHS)	1	3,140.0000	3,140.00 ✓
15	FRONT DOOR (LHS) - REPAIR	1		
16	REAR DOOR (LHS) - REPAIR	1		
17	REAR FENDER (LHS)	1	1,865.0000	1,865.00 ✓
18	REAR FENDER INNER TRIM BOARD CLIPS @ 10PCS	10	5.0000	50.00 ✓
19	REAR BUMPER repair	1	674.0000	674.00
20	REAR BUMPER SIDE RETAINER (LHS)	1	58.0000	58.00
21	REAR BUMPER CLIPS @ 10PCS	10	4.0000	40.00
22	REAR SPORT RIM (LHS) repair	1	1,237.0000	1,237.00

8856.00
1221.20
7084.80

C/F 0.00
Page 1 of 2



PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From :	Customer :
PEGASUS ENGINEERING & TRADING PTE LTD 74 KIAN TECK ROAD SINGAPORE 628800	GRAB RENTALS PTE LTD 3 MEDIA CLOSE #07-03 SINGAPORE 138498
Officer in Charge : VIVIAN TAN EE WI Tel : Email :	Attn : Tel : Fax No. :

Quotation No. : QO24/09-1041	Quotation Date : 05/09/2024	Terms : 60 DAYS
Vehicle No. : SNR5609B	Chassis No. : KMHLN41JVRU112784	Policy Number :
Model : CN7 AVANTE 1.6 Petrol-Electric	Date of Accident : 01/09/2024	
Third Party Insurer : SMRT	TP Vehicle No. : SMB5056S	
Remarks :		

ITEM	DESCRIPTION	Qty	UNIT PRICE	AMOUNT (SGD)
			B/F	0.00
23	REAR WINDSCREEN GLASS MOULDING X	1		
24	LESS 20%	1		
25	REAR WINDSCREEN GLASS SEALANT X	1	80.0000	80.00
26	TO REMOVE & REFOCUS FRONT HEADLAMP.	1	120.0000	30 120.00
27	TO REMOVE & REPLACE RHS FRONT & REAR SPORT RIM & TRANSFER TYRE AND CONDUCT WHEEL BALANCING.	1	150.0000	100 150.00
28	TO CONDUCT WHEEL ALIGNMENT.	1	150.0000	60 150.00
29	TO APPLY RUSTPROOFING/ TUFFCOATING TREATMENT FOR THE REPLACED PARTS.	1	120.0000	60 120.00
30	TO KNOCKING & PANEL BEATING.	1	1,500.0000	1000 1,500.00
31	TO PUTTY & SPRAY PAINT ON THE AFFECTED AREAS.	1	1,600.0000	1200 1,600.00

240.80

P — # 7084.80
 L — # 2450.00
 # 9534.80
 45 — # 7600.00

Rasul
 Hp 90010068
 8 days
 4/3
 09/09/24
 Resy after repair

Sub Total 3,720.00
 GST(9.00%) 334.80
 Total (SGD) 4,054.80

Please conduct the survey at
 Pegasus Engineering @ 74 Kian Teck Road Singapore 628800

202409121456

Pegasus Engineering & Trading PTE LTD

HYUNDAI Model Avante (AE HEV) Hybrid 2024

4-wheel aligner

Plate No. SNR5609B


12-Sep-24

<<Front Wheel>>

Items	Standard Parameters			Measurement	Adjustment
	Min	Std	Max		
Left Camber	-0.88°	-0.38°	+0.12°	+0.23°	-0.35°
Right Camber	-0.88°	-0.38°	+0.12°	-0.63°	-0.40°
Left Caster	+4.00°	+4.50°	+5.00°	+4.95°	+4.96°
Right Caster	+4.00°	+4.50°	+5.00°	+3.78°	+4.60°
Left S.A.I	0.00°	0.00°	0.00°	+15.98°	+15.98°
Right S.A.I	0.00°	0.00°	0.00°	+15.96°	+15.99°
Left Toe	-0.05°	+0.05°	+0.15°	+0.27°	+0.05°
Right Toe	-0.05°	+0.05°	+0.15°	-0.38°	+0.05°

<<Rear Wheel>>

Left Camber	-1.70°	-1.20°	-0.70°	-1.10°	-1.19°
Right Camber	-1.70°	-1.20°	-0.70°	-1.33°	-1.20°
Left Toe	-0.03°	+0.07°	+0.17°	-0.56°	+0.05°
Right Toe	-0.03°	+0.07°	+0.17°	+0.15°	+0.05°



L 12= 1920

L 34= 1925

L 13= 2696

L 24= 2699

Left


+16.20°

I. A.

Right

+15.38°

	✓	✗	⚙	?		✓	✗	⚙	?
Pitman	-	-	-	-	Absorber	-	-	-	-
Axletree	-	-	-	-	Control Arm	-	-	-	-
Strut Rod	-	-	-	-	Steering Arm	-	-	-	-
Equilibrium	-	-	-	-	Steering Wheel	-	-	-	-
Stabilizer	-	-	-	-	Tyre Pressure	-	-	-	-



thank you


Phone No. company telephone: 69042177

Address company address: 9A Lok Yang Way S628628

Customer Name:

Customer TEL:

0 KM



PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From : PEGASUS ENGINEERING & TRADING PTE LTD 74 KIAN TECK ROAD SINGAPORE 628800 Officer in Charge : VIVIAN TAN EE WI Tel : Email :	Customer : GRAB RENTALS PTE LTD 3 MEDIA CLOSE #07-03 SINGAPORE 138498 Attn : Tel : Fax No. :
---	---

Quotation No. : QO24/09-1041	Quotation Date : 05/09/2024	Terms : 60 DAYS
Vehicle No. : SNR5609B	Chassis No. : KMHLN41JVRU112784	Policy Number :
Model : CN7 AVANTE 1.6 Petrol-Electric	Date of Accident : 01/09/2024	
Third Party Insurer : SMRT	TP Vehicle No. : SMB5056S	
Remarks :		

ITEM	DESCRIPTION	Qty	UNIT PRICE	AMOUNT (SGD)
1	FRONT BUMPER <i>SCA /</i>	1		
2	FRONT BUMPER SIDE RETAINER (LHS) ?	1		
3	FRONT BUMPER CLIPS @ 10PCS <i>SCA /</i>	10		
4	FRONT BUMPER "H" LOGO <i>SCA X</i>	1		
5	FRONT BUMPER FOG LAMP COVER (LHS) X	1		
6	FRONT BUMPER FOG LAMP (LHS) X	1		
7	FRONT BUMPER SIDE MOULDING PIECE (LHS) (BLACK COLOUR) <i>SCA /</i>	1		
8	FRONT BUMPER SIDE MOULDING (LHS) (MATT COLOUR) <i>SCA /</i>	1		
9	FRONT BUMPER SIDE AIR DUCT (LHS) X	1		
10	FRONT FENDER (LHS) <i>SCA /</i>	1		
11	FRONT FENDER SPLASH SHIELD (LHS) X	1		
12	FRONT FENDER SPLASH SHIELD CLIPS @ 10PCS X	10		
13	FRONT SPORT RIM (LHS) <i>SCA /</i>	1		
14	FRONT HEADLAMP (LHS) <i>SCA /</i>	1		
15	FRONT DOOR (LHS) - REPAIR	1		
16	REAR DOOR (LHS) - REPAIR	1		
17	REAR FENDER (LHS) <i>SCA /</i>	1		
18	REAR FENDER INNER TRIM BOARD CLIPS @ 10PCS <i>SCA /</i>	10		
19	REAR BUMPER <i>repair</i>	1		
20	REAR BUMPER SIDE RETAINER (LHS) X	1		
21	REAR BUMPER CLIPS @ 10PCS X	10		
22	REAR SPORT RIM (LHS) <i>repair</i>	1		

PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From : PEGASUS ENGINEERING & TRADING PTE LTD 74 KIAN TECK ROAD SINGAPORE 628800 Officer in Charge : VIVIAN TAN EE WI Tel : Email :	Customer : GRAB RENTALS PTE LTD 3 MEDIA CLOSE #07-03 SINGAPORE 138498 Attn : Tel : Fax No. :
--	--

Quotation No. : QO24/09-1041	Quotation Date : 05/09/2024	Terms : 60 DAYS
Vehicle No. : SNR5609B	Chassis No. : KMHLN41JVRU112784	Policy Number :
Model : CN7 AVANTE 1.6 Petrol-Electric		Date of Accident : 01/09/2024
Third Party Insurer : SMRT		TP Vehicle No. : SMB5056S
Remarks :		

ITEM	DESCRIPTION	Qty	UNIT PRICE	AMOUNT (SGD)
			B/F	0.00
23	REAR WINDSCREEN GLASS MOULDING	1	156.0000	156.00
24	LESS 20%	1	-2,329.6000	-2,329.60
25	REAR WINDSCREEN GLASS SEALANT	1	80.0000	80.00
26	TO REMOVE & REFOCUS FRONT HEADLAMP.	1	120.0000	120.00
27	TO REMOVE & REPLACE RHS FRONT & REAR SPORT RIM & TRANSFER TYRE AND CONDUCT WHEEL BALANCING.	1	150.0000	150.00
28	TO CONDUCT WHEEL ALIGNMENT.	1	150.0000	150.00
29	TO APPLY RUSTPROOFING/ TUFFCOATING TREATMENT FOR THE REPLACED PARTS.	1	120.0000	120.00
30	TO KNOCKING & PANEL BEATING.	1	1,500.0000	1,500.00
31	TO PUTTY & SPRAY PAINT ON THE AFFECTED AREAS.	1	1,600.0000	1,600.00

Sub Total	13,038.40
GST(9.00%)	1,173.46
Total (SGD)	14,211.86

Please conduct the survey at
 Pegasus Engineering @ 74 Kian Teck Road Singapore 628800