



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AUTO & GENERAL INSURANCE (S) PL
(BUDGET DIRECT INSURANCE)
190 CLEMENCEAU AVENUE #03-01
SINGAPORE SHOPPING CENTRESINGAPORE
239924
ATTN: MADELEINE LEE

Ref: CS/AGI24090086/Avp3e2(N)

Date: 22/05/2025

Code: AGI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SFW 2916C	Veh. Inspected	SLH 4338R
Policy No.	P11079675R00	Coverage (\$)	0.00
Claim No.	C10031489/ML	Excess (\$)	0.00
Assign From	MADELEINE LEE	Assign Date	04/09/2024

2. Vehicle Particulars & Condition

Make & Model	TOYOTA ALTIS	c.c	1598
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	MR053REH104556289	Colour	WHITE
Odometer	566843 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/45 R17	DUNLOP	6 mm
L/H Front Tyre	215/45 R17	DUNLOP	6 mm
R/H Rear Tyre	215/45 R17	DUNLOP	6 mm
L/H Rear Tyre	215/45 R17	DUNLOP	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	03/09/2024	Inspection Date	05/09/2024
Survey held at	UNIMOTOR COMPANY 1 KAKI BUKIT AVE 6, #01-94 (AUTOBAY @ KAKI BUKIT) SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **5 Working Days**