Not Authorist 1000 1/5 4 7000

SPEEDWERKZ PRIVATE LIMITED

1 KAKI BUKIT AVENUE 6 #01-73, AUTOBAY, SINGAPORE 417883 Tel: 96195936 / info@speedwerkz.biz

VEHICLE NUMBER: SNF6378Z MAKE & MODEL: MG HS

| 2 11 - 0 | 2 | |
|--|----------|----------------|
| TAILGATE B. J. D | 2700 | \$3,121.00 — |
| TAILGATE LOGO Su | | \$215.00 X |
| TAILGATE HS EMBLEM N7 | | \$103.00 📈 |
| TAILGATE INNER LOCK Doge Suf | 305 | \$456.00 |
| TAILGATE STRIKER | | \$55.00 × |
| TAILGATE INNER TRIMBOARD 11 | | \$1,125.00 X |
| TAILGATE WEATHERSTRIP ^ / | | \$194.00 🗴 |
| TAILGATE WINDSCREEN MOULDING SET // | 80 | \$245.00 |
| TAILGATE INNER LAMP L/R X2 MS Cre 2/5 M | 537 | \$1,322.00 (2) |
| TAIL LAMP L/R X2 MS ene 2/5~~ | 9.47 | \$2,212.00 12 |
| REAR BUMPER >2/70-1 | 974 | \$984.00 |
| REAR BUMPER LOWER BLACK | 447 | \$587.00 |
| REAR BUMPER LOWER CHROME SOLVICE D | , | \$413.00 |
| REAR BUMPER SIDE RETAINER L/R X2 | | \$384.00 💉 |
| REAR BUMPER SIDE REFLECTOR L/R X2 | | \$644.00 🗙 |
| REAR BUMPER TOW COVER | | \$48.00 X |
| REAR BUMPER REVERSE SENSOR X4 Molfreton | 185 | \$1,426.00 |
| REAR BUMPER REVERSE SENSOR BRACKET SET | | \$131.00 |
| REAR BUMPER CENTRE BRACKET | | \$287.00 X |
| REAR BUMPER REINFORCEMENT 541-4 | 596. | \$624.00 |
| END PANEL OUTER | 4/0. | \$354.00 × |
| END PANEL INNER | | \$842.00 % |
| END PANEL GARNISH | | \$296.00 × |
| REAR FENDER WHEEL ARCH GARNISH L/R X2/1/ | | \$254.00 0 |
| REAR EXHAUST MUFFLER TIP L/R X2 // | | \$546.00 × |
| REAR EXHAUST MUFFLER | | \$1,421.00 |
| | _ | \$18,289.00 |
| | Less 10% | \$1,828.90 |
| | _ | \$16,460.10 |
| | | +, 100.20 |

| I SEE REAR BUMPER CLIPS | \$60.00 40 S/N |
|---|------------------|
| 1set Raar wags sticker ner | \$380.00 350 S/N |
| TAILGATE TRIMBOARD CLIPS | \$50.00 \$ |
| TAILGATE WINDSCREEN SEALANT | \$120.00 40 5/N |
| TAILGATE WINDSCREEN SPONGE | \$80.00 21 (1) |
| END PANEL GARNISH CLIPS | \$60.00 × |
| END PANEL SEALANT | \$100.00 × |
| REAR FENDER WHEEL ARCH GARNISH CLIPS L/R X2 | \$200.00 > |
| REAR NUMBER PLATE WITH CASING TWO | \$70.00 Hp S/n) |
| () | \$1,120.00 |

| TO CHECK REAR WIRING TO REPLACE REAR REVERSE SENSOR TO REPLACE REAR REVERSE CAMERA TO REPLACE REAR WINDSCREEN TO REMOVE AND REPLACE TAILGATE FITTINGS TO REMOVE AND REPLACE REAR INTERIOR TRIMS & GARNISH | \$60.00 20 \$120.00 40 11 \$100.00 X \$150.00 1 20 \$120.00 50 \$200.00 60 |
|---|---|
| TO PROVIDE LABOUR, WORKMANSHIP TO SPRAY PAINT ON AFFECTED PANELS | \$1,500.00 550 |
| TO REMOVE AND REPLACE REAR EXHAUST MUFFLER | \$1,200.00 750 |
| RUST PROOFING | \$120.00 X \$150.00 3 O |
| TO REPROGRAMME AND CALIBRATE SYSTEM | ^ <u>↑</u> \$250.00 × |
| | \$3,970.00 |

Total

\$21,550.10

LKK Auto Consultants hence notify

- To recurvey before/after spray pointing
- To display damaged part(s), in the real
- Parts prices are subject to confineation
- Third party survey is on a "Without Projude." book
- No illegal modification(s) is allowed
- Supplementary item(s) must be resummed and is subject to final approval from Insurance Comment.

Acknowledged by Renairer

Signature

Dale:

P-740 102 6673:50 490 1620 7783:50 202