

F0001

KOMOCO MOTORS PTE LTD

2nd Floor, 100, North Bridge Road, Singapore 079206
 Tel: 65473388 Fax: 65473389 Email: info@komoco.com.sg
 012 445 9665/576

GST REGISTRATION NO: MR-8500364-4)

Date :

INDIA INTERNATIONAL INSURANCE Pte Ltd

Attn: Motor Claims Department

Vehicle number : SMT4486X
 Make and model : IONIQ 1.6 DCT HYBRID
 Registration Date : 16/04/2024
 Chassis number : KMHC851CVLU219690
 Engine number : G4LELU538300

Claim Officer : Robyn

Job No. :

Owner name : KOMOCO CAR REI

Date of Acc : 04/09/2024

Policy number : B400002657MCY

Claim Type : tp

Items :

2nd

Estimate

Revised

1	FRT BUMPER CLIP X10 <i>cm</i>	865952T500
2	COVER-FR BUMPER <i>de</i>	86511G2500
3	MOULDING-FRONT BUMPER CTR,UPR <i>sa</i>	86585G2500
4	MOULDING-FRONT BUMPER,RH <i>sa</i>	86564G2550
5	DUCT ASSY-AIR CURTAIN,RH <i>? Xsur</i>	86568G2500
6	LAMP ASSY-DAY RUNNING LIGHT,RH <i>? Xsur</i>	92208G2100
7	PANEL-FENDER,RH <i>regr</i>	66321G2000
8	CARRIER ASSY-FRONT END MODULE <i>? cm</i>	64101G2000
9	BEAM COMPLETE-FR BUMPER <i>? Xsur</i>	64900G2000
10	STIFFNER-FR BPR LWR <i>? Xsur</i>	86571G2000
11	BRACKET-FR BUMPER SIDE,RH <i>Re</i>	86514G2000
12	LAMP ASSY-HEAD,RH <i>cm</i>	92102G2230

	\$	20.00 ✓
	\$	554.00 ✓
	\$	345.00 ✓
	\$	55.00 ✓
	\$	13.00
	\$	643.00
	\$	589.00
	\$	950.00 ✓
	\$	1,484.00
	\$	86.00
	\$	20.00 ✓
	\$	2,111.00 ✓

less 20%
 Less ~~25%~~ Discount
 Material total

\$ 6,870.00

\$ 1,717.50

\$ 5,152.50

due 03/10.

LKK. 19/9/24

ie number

Body, Paint & Labour Items :

		Estimate
1	To carry out accident body repair - FRT BUMPER / FRT FENDER / SUPPORT PANEL	\$ 2,760.00 920 - 1380
2	Complete putty and spray paint all affected areas - FRT BUMPER / FRT BUMPER GARNISH RHS / FRT RH FENDER / FRT BUMPER GARNISH / FRT BONNET	\$ 2,000.00 1140 + 1100 = 1240

Labour Charges:

	2nd	Estimate	Revised
3	TO REALIGN FRT BOTH HEADLAMP (S.NETT)	\$ 40.00	
4	TO REPAIR FRT RH FENDER APRON (S.NETT)	\$ 460.00	
5	TO TOP UP A/C GAS (S.NETT)	\$ 140.00	X 27
6	TO REPAIR FRT CHASIS MEMBER (S.NETT)	\$ 460.00	X 27
7	TO RECALIBRATE FRT RADAR SENSOR (S.NETT)	\$ 460.00	X 27
8	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING AFTER ACCIDENT REPAIR (S.NETT)	\$ 180.00	
9	TO PERFORM PREPROGRAMME AFTER ACCIDENT REPAIR (S.NETT)	\$ 180.00	
10	SUNDRIES	\$ 40.00	
Total Labour		\$ 6,720.00	
Total Parts		\$ 5,152.50	
Excess		\$ -	
		\$ 11,872.50	
Add GST 9%		\$ 1,068.53	
Grand Total		\$ 12,941.03	

Rame
 Hp 50010068
 4 days
 11/09/24
 Reg 64 paint

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: