



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SNJ 1825L

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	REAR BUMPER	DEFORMED	\$1,430.00	\$1,430.00
1	REAR BUMPER SIDE HOLDER	NOT NECESSARY	\$160.00	\$0.00
1	REAR RH FENDER	TO REPAIR SEE LABOUR	\$1,730.00	\$0.00
1	REAR RH FENDER INNER SHIELD	NOT NECESSARY	\$165.00	\$0.00
1	REAR RH DOOR	DENTED	\$1,370.00	\$1,370.00
1	REAR RH SPORT RIM	CUT	\$1,045.00	\$1,045.00
1	REAR RH TYRE	NOT NECESSARY	\$380.00	\$0.00
1	REAR RH LOWER ARM	BENT	\$305.00	\$305.00
1	REAR RH KNUCKLE ARM	DAMAGED	\$1,195.00	\$1,195.00
1	REAR RH KNUCKLE ARM BEARING	DAMAGED	\$575.00	\$575.00
	LESS 5.00% DISCOUNT		(\$417.75)	(\$296.00)
			\$7,937.25	\$5,624.00
Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	BODY STICKER		\$1,300.00	\$500.00
	TO CHECK WHEEL ALIGNMENT		\$100.00	\$80.00
	REMOVE + REINSTALL REVERSE SENSOR		\$150.00	\$50.00
	REMOVE + REINSTALL REAR RH SUSPENSION		\$400.00	\$150.00
	REMOVE + REINSTALL DOOR GLASS		\$100.00	\$60.00
	REMOVE, REPLACE + REPAIR CONSISTENT TO THE ACCIDENT. INCLUSIVE OF THE REPAIR OF REAR RH FENDER		\$1,200.00	\$500.00
	RESPRAY PAINTING		\$1,000.00	\$600.00
			\$4,250.00	\$1,940.00
GRAND TOTAL			\$12,187.25	\$7,564.00
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			\$6,000.00
Report Ref No: CS/FCI24090099/Aqp3m4				



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

LWP

ADRIAN LING WAI PING

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.