








PHOTOGRAPHS FOR VEHICLE NO. : SNJ 1825L



PHOTOGRAPHS FOR VEHICLE NO. : SNJ 1825L



PHOTOGRAPHS FOR VEHICLE NO. : SNJ 1825L





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

INSPECTION PHOTOS (Page 4 of 10)


PHOTOGRAPHS FOR VEHICLE NO. : SNJ 1825L



PHOTOGRAPHS FOR VEHICLE NO. : SNJ 1825L




PHOTOGRAPHS FOR VEHICLE NO. : SNJ 1825L




PHOTOGRAPHS FOR VEHICLE NO. : SNJ 1825L



PHOTOGRAPHS FOR VEHICLE NO. : SNJ 1825L



PHOTOGRAPHS FOR VEHICLE NO. : SNJ 1825L





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

INSPECTION PHOTOS (Page 10 of 10)

PHOTOGRAPHS FOR VEHICLE NO. : SNJ 1825L

