



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD 16 RAFFLES QUAY #42-01 HONG LEONG BUILDINGSINGAPORE 048581		Ref: CS/FCI24090103/Tvp3e2(N) Date: 07/01/2025 Code: FCI2	
1. Policy Particulars :- OWN DAMAGE			
Insured Veh.		Veh. Inspected	XE 5739J
Policy No.		Coverage (\$)	0.00
Claim No.	D24007775MFVS/OD/KT	Excess (\$)	7,500.00
Assign From	KAREN TAN	Assign Date	04/09/2024
2. Vehicle Particulars & Condition			
Make & Model	ROSENBAUER PANTHER 6X6	c.c	16123
Engine No.	HIDDEN	Year of Reg.	2020
Chassis No.	VA96WK689KLRB1164	Colour	RED
Odometer	-	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	445/80 R25	MICHELIN	8 mm
L/H Front Tyre	445/80 R25	MICHELIN	8 mm
R/H Rear Tyre	445/80 R25	MICHELIN	8 mm
L/H Rear Tyre	445/80 R25	MICHELIN	8 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	02/09/2024	Inspection Date	05/09/2024
Survey held at	AIRPORT MAINTENANCE CENTRE 7 ABINGDON BLK 1		
Repairer	STRIDES PREMIER AUTOMOTIVE SERVICES PL		
5a. Remarks			
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE MARKET VALUE IS S\$1,300,000.00(EST. AVERAGE) C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		40 Working Days	