



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS INCOME INSURANCE LTD	Ref:	CS/INC24090105/Avh3
75 BRAS BASAH ROAD	Date:	24/09/2024
INCOME CENTRE SINGAPORE 189557	Code:	INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKR 6647U	Veh. Inspected	SMG 1730D
Policy No.	-	Coverage	0
Claim No.	MT/1292855-002	Excess	\$0.00
Assign From	CHARLOTTE	Assign Date	05/09/2024

2. Vehicle Details

Make & Model	TOYOTA NOAH HYBRID	C.C	1797
Engine No.	2ZR0C19023	Year of Reg.	29/11/2018
Chassis No.	ZWR800339497	Colour	WHITE
Odometer	152640 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	195/65R15	MICHELIN	6
L/H Front Tyre	195/65R15	MICHELIN	6
R/H Rear Tyre	195/65R15	MICHELIN	6
L/H Rear Tyre	195/65R15	MICHELIN	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	28/08/2024	Inspection Date	09/09/2024 (13:00)
Survey held at	HUA MENG SPRAY PAINTING WORKSHOP 1 KAKI BUKIT AVE 6 #01-61 AUTOBAY SINGAPORE 417883		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days