
BLUWEL AUTOMOTIVE SERVICE PTE LTD 1 KAKI BUKIT AVE 6 # 01-28/53/55/56 SINGAPORE 417883 TEL: 67452088

VEHICLE No: SNH 3649B

Not Anthorael
de
maras 6/9/24
4/3 # 2100
3 days.
Theshe Ath 1 ye
- Cimpon !!

1PC	REAR BUMPER	20/00		\$1,143.51
1PC	REAR BUMPER LOWER DIFFUSER	De /10:00		\$820.00
1PC	REAR BUMPER BEAM	2		\$399.75 🗶
2PCS	REAR BUMPER SIDE RETAINERS @\$46.	50 n 1		\$93.00 ×
1SET	REAR BUMPER CLIPS	M		\$50.00
1PC	REAR BUMPER PDC SENSOR	su		\$250.00 0
1SET	REAR BUMPER PDC SENSOR BRACKETS	ner		\$50.00
1PC	REAR LICENCE PLATE W/HOLDER	sut		\$50.00
1PC	REAR END PANEL	R		\$547.00 X
1PC	REAR END PANEL TOP GARNISH	11		\$262.30 ×
				\$3,665.56
			LESS 20%	\$2,932.45

TO CHECK WIRING	\$50.00 20		
TO DISMANTLE & REFIX REAR PDC SENSOR	\$80.00 4,7		
TO TRANSFER BOOTLID MECHANISM	47 \$80.00 X		
TO DISMANTLE & REFIX CUSHION UPHOLSTERY	1つ \$120.00 人		
TO SPRAY RUST PROOFING	∧< \$50.00 ×		
LABOUR FOR PANEL BEATING & REPLACED PARTS	\$880.00 300		
TO PUTTY & SPRAY PAINTING	\$1,000.00 600		
	TOTAL \$5,192.45		



960

2120