

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTTokio Marine Insurance Singapore Ltd
20 McCallum Street, #09-01 Tokio Marine Centre
Singapore 069046**Our File No:** CS/TMI24090111/PQP3E2**Date:** 26/09/2024REFERENCE**Insured/Claimant:** CHUAN HONG SENG TRADING
Date of Loss: 02/08/2024**Policy No:** MZC04880
Nature of Claim: OD **Claim No:** M2404769DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBK6307U	Engine No:	HR16175277D
Make & Model:	NISSAN NV200, 1.6 DX (A)	Chassis No:	VM20160428
Reg. Date:	28/09/2020 (Man. Year: 2020)	Odometer:	0 km
Colour:	White		
Engine Capacity:	1597 cc		
Market Value/New Car Price:	S\$59,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Poor	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Poor

CONDITION OF TYRES

Front Tyre Size:	175/70 R14	Rear Tyre Size:	175/70 R14
Front Left Side:	KAPSEN 0 mm	Rear Left Side:	KAPSEN 4 mm
Front Right Side:	KAPSEN 0 mm	Rear Right Side:	KAPSEN 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	12.00	12.00	0.00	0.00
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12.00	12.00	0.00	0.00
- Excess (S\$)	0.00	3,100.00	-3,100.00	
(S\$)	12.00	-3,088.00	3,100.00	25,833.33
+ GST 9.00/0.00% (S\$)	1.08	0.00	1.08	100.00
Nett Amount (S\$)	13.08	-3,088.00	3,101.08	23,708.56

INSPECTION

Date of Assignment:	06/09/2024	Present Location:	MBM Wheelpower Pte Ltd (HQ)
Date Inspected:	06/09/2024	Inspected At:	MBM Wheelpower Pte Ltd (HQ)
Estimated Period of Repair:	0.0 days		160 Sin Ming Drive #06-02, Sin Ming AutoCity
			Singapore 575722

Adjuster: Sherwin Beh Swee Yang**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

TOTAL LOSS ASPECT

Market Value :	\$59,000.00
OMV :	\$22,537.00
PARF Rebate (1) :	\$ 0.00
Quota Premium Paid :	\$24,963.00
COE Rebate (2) :	\$15,123.00
Total Rebate (1) + (2) = :	\$15,123.00

The total amount incurred will be Market Value \$59,000.00 minus Total Rebate \$15,123.00 = \$43,877.00 before excess.

In view of the above, the vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 26 Sep 2024)	
Parts:	N/A	NISSAN NV200 1.6 DX (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBK6307U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	OD/TP Case (Insurer)	12.00	12.00
			Sub Total (\$)	12.00

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >