

Note: This document has not been finalised.
LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: Tokio Marine Insurance Singapore Ltd
20 McCallum Street
#09-01 Tokio Marine Centre
Singapore 069046

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Tang Hock Lye Ben

Date: 09 Sep 2024

Preliminary Advice

Vehicle No	: GBK6307U	Accident Date	: 02/08/2024
Make	: NISSAN NV200	Policy No.	: MZC04880
Assignment Date	: 06/09/2024	Excess	: S\$3,100.00
Date of Inspection	: 06/09/2024	Est. Duration of Repair	: 0
Inspection At	: MBM WHEELPOWER PTE LTD (HQ) 160 SIN MING DRIVE #06-02, SIN MING AUTOCITY SINGAPORE 575722		

Point of Impact / General Description of Damages

The vehicle caught fire.

Repairer's Estimate (Gross)	:S\$	TOTAL LOSS
Revised Amount	:S\$	TOTAL LOSS
Check Items (Estimated)	:S\$	
Total	:S\$	
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	59,000.00
COE / PARF Rebate	:S\$	15,123.00
Salvage Value	:S\$	
Margin for Repair	:S\$	43,877.00

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- (X) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : PENDING FOR INVESTIGATION.
Kindly advise on SCDF fire report applying as have additional charge