

Main Office:
Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:
Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722

Tel: (65) 6272 3892
Fax: (65) 6270 8314
Co. Reg. 198904033G
GST Reg. M2-0088864-2

ESTIMATE

5/9/2024

INDIA INT'L INSURANCE PTE LTD
64 CECIL STREET
#04-06 IOB BUILDING
SINGAPORE 049711.

Vehicle No: GBG8922B
Vehicle Model: MIT L200
Est No: CBMQ24090045
Claims ref:
Accident Date: 04/09/24
In Charge: BILLY
Remarks:

No	Description	Qty	U. Price	Amounts S\$
LIST ITEMS:				
1	TAILGATE <i>bt</i>	1	PC \$ 1,177.00	\$ 1,177.00
2	TAILGATE EMBLEM - L200 <i>ne</i>	1	PC \$ 38.00	\$ 38.00
3	TAILGATE EMBLEM - SPORTER <i>ne</i>	1	PC \$ 58.00	\$ 58.00
4	TAILGATE LOGO <i>ne</i>	1	PC \$ 45.00	\$ 45.00
5	TAILGATE EMBLEM - DHD <i>ne</i>	1	PC \$ 29.00	\$ 29.00
6	TAILGATE EMBLEM - COMMON RAIL <i>ne</i>	1	PC \$ 42.00	\$ 42.00
7	TAILGATE EMBLEM - C&C <i>ne</i>	1	PC \$ 55.00	\$ 55.00
8	TAILGATE OUTER HANDLE <i>scu</i>	1	PC \$ 65.00	\$ 65.00
9	TAILGATE HINGE RH & LH <i>X</i>	2	PC \$ 59.00	\$ 118.00
10	THIRD BRAKE LIGHT <i>scu</i>	1	PC \$ 250.00	\$ 250.00
11	TAILLAMP ASSY RH & LH <i>X</i>	1	PC \$ 242.00	\$ 242.00
12	REAR END PANEL <i>refur</i>	1	PC \$ 580.00	\$ 580.00
13	REAR END PANEL STOPPER RH & LH <i>X</i>	2	PC \$ 15.00	\$ 30.00
14	REAR FENDER RH & LH (REPAIR) <i>X</i>	2	PC	\$ -
LIST TOTAL S\$				\$ 2,729.00
10% DISCOUNT S\$				\$ (272.90)
				<u>\$ 2,456.10</u>

SPECIAL NET ITEMS:

1	TAILGATE STICKER - 70KM/H <i>ne</i>	1	PC \$ 10.00	\$ 10.00
2	REAR NUMBER PLATE <i>scu</i>	1	PC \$ 40.00	\$ 40.00
3	REVERSE SENSOR <i>cm</i>	1	PC \$ 200.00	\$ 200.00

SPECIAL NET TOTAL S\$

\$ 250.00

LABOUR CHARGE:

- TO CUT / WELD REAR END PANEL, KNOCK & STRAIGHTEN REAR FENDER RH & LH, REMOVE & REPLACE ACCIDENT DAMAGED PARTS, REALIGN

Main Office:

Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:

Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722

Tel: (65) 6272 3892
Fax: (65) 6270 8314

Co. Reg. 198904033G
GST Reg. M2-0088864-2

ESTIMATE

5/9/2024

INDIA INT'L INSURANCE PTE LTD

64 CECIL STREET

#04-06 IOB BUILDING

SINGAPORE 049711.

Vehicle No: GBG8922B

Vehicle Model: MIT L200

Est No:CBMQ24090045

Claims ref:

Accident Date: 04/09/24

In Charge: BILLY

Remarks:

No	Description	Qty	U. Price	Amounts S\$
	ALL CONNECTION			\$ 1,000.00 400 500
2	SPRAY PAINT TAILGATE, REAR END PANEL, REAR FLOOR PANEL, REAR FENDER RH & LH			\$ 1,200.00 400 500
3	REMOVE & REPLACE REVERSE SENSOR & CHECK FUNCTION			\$ 80.00 40
4	RUST PROOF AFFECTED AREAS			\$ 50.00 30
	TOTAL LABOUR COST S\$			\$ 2,330.00

AMOUNT S\$ \$ 5,036.10

GST @ 9% \$ 453.25

AMOUNT DUE S\$ \$ 5,489.35

Customer's Signature

MOVA AUTOMOTIVE PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Same
Hp 90010068
4 days
L/S
18/09/24
Pay after repi-