

# FALCON AIR AUTO SERVICES PTE LTD

Tel No. :

SPF ACCIDENT CLAIMS SECTION  
1 MOUNT PLEASANT ROAD  
BLK 8 OLD POLICE ACADEMY 298333

Attention : Motor Claim Department

Estimate : ES709618

Date : 09/09/2024

Vehicle Num. : YR 2144P

Make/Model : TOYOTA DYNA

Chassis/Eng# :

Accident Date : 03/09/2024

Claim No. :

Reference :

Policy No. :

not Authorized  
nkl  
mores

9/5/24

2/5 = 4500

Tel. ph. Attn. my

3 days

| S/N | Quantity | Particular | Unit Price | Amount S\$ |
|-----|----------|------------|------------|------------|
|-----|----------|------------|------------|------------|

|              |     |                          |         |          |
|--------------|-----|--------------------------|---------|----------|
| LIST ITEMS : |     |                          |         |          |
| 1.           | 1PC | FRONT BUMPER             | 865.90  | 1,092.90 |
| 2.           | 1PC | O/S FRONT BUMPER BRACKET |         | 417.32   |
| 3.           | 1PC | O/S HEADLAMP             | 1759.80 | 2,939.40 |
| 4.           | 1PC | O/S STEP GARNISH         |         | 459.40   |
| 5.           | 1PC | RADIATOR GRILLE          |         | 906.30   |
| 6.           | 1PC | RADIATOR GRILLE BASE     |         | 272.00   |
| 7.           | 1PC | O/S FRONT DOOR           | 2681.60 | 2,739.00 |

List TotalS\$ :

25.00% Discount S\$ :

8,826.32

2,206.58

6,619.74

|                      |      |                      |       |       |
|----------------------|------|----------------------|-------|-------|
| SPECIAL NETT ITEMS : |      |                      |       |       |
| 1.                   | 1SET | RADIATOR GRILLE CLIP | 50.00 | 50.00 |
| 2.                   | 1PC  | FRONT NUMBER PLATE   | 50.00 | 50.00 |

Special Nett Total S\$ :

100.00

LABOUR :

TO CHECK LIGHT AND WIRING  
TRANSFER DOOR PARTS

50.00

100.00

CONTINUE / ...

# FALCON AIR AUTO SERVICES PTE LTD

Tel No. :

SPF ACCIDENT CLAIMS SECTION  
1 MOUNT PLEASANT ROAD  
BLK 8 OLD POLICE ACADEMY 298333

Attention : Motor Claim Department

Estimate : ES709618

Date : 09/09/2024  
Vehicle Num. : YR 2144P  
Make/Model : TOYOTA DYNA  
Chassis/Eng# :  
Accident Date : 03/09/2024  
Claim No. :  
Reference :  
Policy No. :

| S/N | Quantity | Particular                            | Unit Price | Amount S\$ |
|-----|----------|---------------------------------------|------------|------------|
|     |          | LABOUR/PANEL BEATING- REPAIR A PILLAR |            | 600.00 350 |
|     |          | SPRAY PAINTING                        |            | 800.00 550 |
|     |          | Labour Total S\$ :                    |            | 1,550.00   |

E. &amp; O.E.

Total S\$ : 8,269.74

=====

for FALCON AIR AUTO SERVICES PTE LTD

TAMPINES BRANCH

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

p- 6184.02  
252  
4638.02  
30  
970  
4638.02  
222  
4810.02