



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

MS LIBERTY INSURANCE PTE LTD	Ref:	CS/LIP24090133/Uvh3
ONE RAFFLES QUAY #25-01 NORTH TOWER	Date:	03/10/2024
SINGAPORE 048583	Code:	LIP

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SDR 1248D	Veh. Inspected	SLB 8129H
Policy No.	-	Coverage	0
Claim No.	IVS24/1702	Excess	\$0.00
Assign From	TED	Assign Date	09/09/2024

### 2. Vehicle Details

Make & Model	HONDA JAZZ 1.5 (A)	C.C	1498
Engine No.	L15B31021023	Year of Reg.	11/05/2016
Chassis No.	JHMGK5850GX202572	Colour	SILVER
Odometer	153417 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

### 3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	205/50R16	GOODYEAR	6
L/H Front Tyre	205/50R16	GOODYEAR	6
R/H Rear Tyre	205/50R16	GOODYEAR	6
L/H Rear Tyre	205/50R16	GOODYEAR	6

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.

DAMAGES SEE DETAILS.

### 5. General Information

Accident Date	04/09/2024	Inspection Date	10/09/2024
Survey held at	TICK HAI MOTOR & WELDING SERVICES BLK 1 KAKI BUKIT AVE 6 #01-54 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		

### 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.  
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days