

Date: 5-9-2024
Vehicle No: SNG5671C
Model: Tesla Model 3
Chassis: LRW3F7FS2NC601751
Reg.Year: 18.8.2022

NOT Authorized
Anthony B4pain
4 days
4225-86

Third Party Insurer: AIG
Third Party Veh No: SMR657G
Date of Accident: 5/9/2024
Estimator: Loong
Surveyor:

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	FRONT BUMPER	1		<i>Bu</i> \$766.00 ✓
2	FRONT RH BUMPER RETAINER	1		<i>na</i> \$1.86 ✓
3	FRONT RH BUMPER SIDE SUPPORT BRACKET	1		<i>cm</i> \$12.14 ✓
4	FRONT RH BUMPER FOG LAMP COVER	1		<i>na</i> \$6.54 ✓
5	FRONT PARKING SENSOR	1		<i>shw</i> \$163.55 ✓
6	FRONT BUMPER LOWER	1		<i>na</i> \$186.91 X
7	FRONT BUMPER ENERGY ABSORBER	1		<i>na</i> \$46.72 ✓
8	FRONT RH FENDER PANEL	1		<i>Bu</i> \$448.60 ✓
9	FRONT RH FENDER LINER	1		<i>cm</i> \$116.82 ✓
10	FRONT RH HEADLAMP	1		<i>mg cm</i> \$1,741.00 ✓
11	FRONT RH WHEEL RIM COVER	1		<i>na</i> \$32.40 X
12	FRONT RH WHEEL RIM	1		<i>na</i> \$505.00 X
13	FRONT RH KNUCKLE ARM	1		<i>na</i> \$420.56 X
14	FRONT RH KNUCKLE HUB + BEARING	1		<i>na</i> \$233.64 X
15	FRONT RH LOWER ARM - STRAIGHT	1		<i>na</i> \$242.99 X
16	FRONT RH LOWER ARM - CURVED	1		<i>na</i> \$224.29 X
17	FRONT RH UPPER ARM	1		<i>na</i> \$121.49 X
18	FRONT RH STEERING TIE ROD END	1		<i>na</i> \$121.49 X
SUB TOTAL				\$5,392.00
LESS 10%				-\$539.20
PARTS TOTAL				\$4,852.80

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	FRONT BUMPER CLIPS	1		<i>na</i> \$55.00 ✓
2	FRONT BUMPER LOWER CLIPS	1		<i>na</i> \$50.00 X
3	FRONT FENDER LINER CLIPS	1		<i>na</i> \$50.00 ✓
4	FRONT PARKING SENSOR MOUNTING BRACKET SET	1		<i>na</i> \$200.00 ✓
S/N TOTAL				\$355.00

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST FRONT ACCIDENT AREAS & ETC. \$700.00 *400*

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT FRONT BUMPER, FRONT RH FENDER, ETC \$650.00 *440*

Date: 5-9-2024
 Vehicle No: SNG5671C
 Model: Tesla Model 3
 Chassis: LRW3F7FS2NC601751
 Reg.Year: 18.8.2022

Third Party Insurer: AIG
 Third Party Veh No: SMR657G
 Date of Accident: 5/9/2024
 Estimator: Loong
 Surveyor:

LABOUR CHARGES TO REMOVE & REPLACE FRONT PARKING SENSOR & ETC.	\$100.00	601
TO TUFF KOTE & UNDERSEAL MATERIALS.	\$100.00	301
TO REMOVE AND REFIT FRONT UNDERCARRIAGE PARTS TO ENABLE REPAIR	nn \$300.00	X
TO CHECK WIRING & ELECTRICAL SYSTEM.	\$100.00	201
TO CONDUCT TYRE BALANCING AND WHEEL ALIGNMENT	nn \$120.00	X
TO R&R TYRE RIM	nn \$100.00	X
TO READJUST AND REALIGN HEADLAMP AIM	\$100.00	401
	LABOUR TOTAL	\$2,270.00
TOTAL		\$7,477.80

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:



> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	677H
Vehicle Details	
Vehicle No.:	SNG5671C
Vehicle to be Exported:	No
Intended Deregistration Date:	06 Sep 2024
Vehicle Make:	TESLA
Vehicle Model:	MODEL 3 RWD
Primary Colour:	White
Manufacturing Year:	2022
Engine No.:	-
Chassis No.:	LRW3F7FS2NC601751
Maximum Power Output:	208.0 kW (278 bhp)
Open Market Value:	\$58,311.00
Original Registration Date:	18 Aug 2022
First Registration Date:	18 Aug 2022
Transfer Count:	0
Actual ARF Paid:	\$31,960.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	17 Aug 2032
PARF Rebate Amount:	\$23,970.00
Intended COE Rebate Details	
COE Expiry Date:	17 Aug 2032
COE Category:	B - Car-Details at OneMotoring
COE Period(Years):	10
QP Paid:	\$100,684.00
COE Rebate Amount:	\$80,005.00
Total Rebate Amount:	\$103,975.00
Message	
You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE.	

The information contained herein is correct as at 05 Sep 2024

OK