

TECHNO AUTOMOTIVE PTE LTD

60 JALAN LAM HUAT #05-56
CARROS CENTRE
SINGAPORE 737869
TEL: 81870013

Estimate for SFM13Z(Lexus ES Hybrid)

*FRONT BUMPER *cur/ym*
*FRONT BUMPER SIDE RETAINER *Sec*
*HEADLAMP HID LH *CN*
*HEADLAMP LOWER BRACKET LH *nn*
*FRONT FENDER LH *20/3nt*
*FRONT FENDER COWLING LH *Sec*
*FRONT WHEEL RIM LH *cur/napah*
*FRONT SHOCK ABSORBER LH *nn*
*FRONT UPPER ARM LH *nn*
*FRONT LOWER ARM LH *nn*
*FRONT KNUCKLE ARM v *nn*
*FRONT STEERING RACK AND PINION *nn*
*FRONT WHEEL HUP WITH BEARING LH *nn*

Less 10%

1 set *FRONT BUMPER CLIP *nn*
*FRONT FENDER COWLING CLIPS LH *nn*
*FRONT WHEEL TYRE RH *Sec*
*FRONT DOOR INNER TRIM CLIP SET *nn*
*REAR DOOR INNER TRIM CLIP SET *nn*

CUT OFF AND REPLACE REAR RHS FENDER. RESTRUCTURE CENTER
CRASH MANAGEMENT COMPONENT AND RENEW OTHER DAMAGE
PARTS
SPRAY PAINTING ON DAMAGE AND AFFECTED AREA
DISMANTLE AND REPLACE FRONT UNDER-CARRIAGE COMPONENTS
APPLY TUFF COATING TREATMENT
PERFORM DIAGNOSTIC CHECK
WHEEL ALIGNMENT

Total

LKK Auto Consultants hence notify
the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) for resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

not item

\$1,359.00
\$114.00 X
\$6,854.00
\$215.00 X
\$1,125.60
\$285.00 X
\$2,514.00
\$765.00 X
\$665.00 X
\$691.50 X
\$1,445.00 X
\$4,874.00 X
\$694.00 X
\$21,601.10
\$2,160.11
\$19,440.99

\$65.00
\$39.00 X
\$680.00 X
\$80.00 X
\$80.00 X
\$944.00

\$1,200.00
\$1,200.00
\$300.00
\$100.00
\$300.00
\$250.00
\$3,350.00

\$23,734.99

*not Authorized
an
merous
10/9/24
1/5 \$5900/
3 days
who ph. Ateng*

4178.50

*P-6663.1
112
5996.79
640
790
7420.79
20
5541*