

ComfortDelGro Engineering Pte Ltd

(Co.Reg.No:199506048W)

59 Loyang Drive
Singapore 508969
Tel: 6214 8300

TP INSURER: Tokio Marine Insurance Singapore Ltd (HQ)
ASIA EXPRESS CAR RENTAL PTE. LTD.

Singapore

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:	MAB00167	Date of Loss:	06/09/2024
Vehicle Reg. No.:	SHD3858G	Driveable?	YES
Party At Fault:	UNKNOWN		

Make/Model:	HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A)	Vehicle Reg. Date:	11/12/2018
Vehicle Colour:	BLUE	Gen Condition:	GOOD
Engine No:	LEB5616009	Chassis No:	GB71079798
Odometer:	0 KM		

Paint Type:	
List Item Discount:	20.00 %
Total Loss?	NO
Est. Duration of Repair (day)	4

Description of Accident/Loss	ACCIDENT INVOLVING SMJ5103Y & SHD3858G ALONG SIMEI STREET 3
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)

COST OF CLAIMS

	Amount
Parts	3,626.36
Miscellaneous Items	12.00
Labour	1,500.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	5,138.36
+ GST 9.00% (S\$)	462.45
Nett Amount (S\$)	5,600.81

This claim is handled by: JUMANI BIN MASUDIN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference**

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 10 Sep 2024)

Parts: 192 HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: ComfortDelGro Engineering Pte Ltd/SHD3858G/10/09/2024 10:47

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRT BUMPER ASSY / BR	20.00	0.00	*481.10 FL
2	10		*FRT BUMPER CLIPS / DEC	20.00	0.00	*22.00 FL
3	1		*FRT BUMPER UPPER MOULDING / CUT	20.00	0.00	*368.50 FL
4	1		*FRT FENDER LH XR	20.00	0.00	*588.80 FL
5	1		*FRT FENDER EMBLEM LH X nm	20.00	0.00	*26.60 FL
6	1		*FRT FENDER SHIELD LH X nm	20.00	0.00	*164.70 FL
7	1		*HEADLAMP ASSY LH / CUT	20.00	0.00	*2,110.30 FL
8	1		*FRT BUMPER BRACKET LH X nm	20.00	0.00	*35.00 FL
9	1		*FRT FOG LAMP LH / CUT	20.00	0.00	*642.50 FL
10	1		*FRT FOG LAMP GRILLE LH / CUT	20.00	0.00	*93.45 FL

F=Franchise part, L=ListItemDisc.

Sub Total (\$\$) **4,532.95**

- List Item Discount on L Items (\$\$) **906.59**

Total Parts (\$\$) **3,626.36**

ComfortDelGro Engineering Pte Ltd/SHD3858G/10/09/2024 10:47. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	OD/TP Case (Insurer)	12.00
Sub Total (S\$)			12.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	PANEL BEATING	New 380	800.00
2	SPRAYPAINT CHARGES	New 580	600.00
3	TUFF KOTE	New X	50.00
4	CHECL WIRING	New 30	50.00
Gross Labour Cost (S\$)			1,500.00

ComfortDelGro Engineering Pte Ltd/SHD3858G/10/09/2024 10:47. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

stere (LKK)

9/9/24, 3-30 pm

without Prejudice
L/s

Resurvey After Spray
2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: