

JL Perfect Autowork Pte Ltd

Company Reg No: 202136905K

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778
E-mail:jlperfectautowork@gmail.com



DATE : 04.09.2024

TO : **CHINA TAIPING** MOTOR CLAIM
VEHICLE NO : **SNQ3146M**
MODEL : **TOYOTA VOXY HYBRID**
DATE OF ACCIDENT : 22.08.2024
TIME OF ACCIDENT : 11:22 HOURS

Yan.

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	SLIDING DOOR RH <i>Dented</i>	1	\$ 1,585.00	\$ 1,585.00
2	SLIDING DOOR STRIP SENSOR RH <i>new</i>	1	\$ 971.50	\$ 971.50
3	SLIDING DOOR OUTER STRIP RH <i>new</i>	1	\$ 1,300.00	\$ 1,300.00
4	SLIDING DOOR FRONT INNER LOCK RH <i>new</i>	1	\$ 618.10	\$ 618.10
5	SLIDING DOOR INNER TRIM RH <i>cracked</i>	1	\$ 1,897.40	\$ 1,897.40
6	SLIDING DOOR FRAME WEATHER STRIP RH <i>new</i>	1	\$ 577.40	\$ 577.40
7	SLIDING DOOR STEP PANEL RH <i>new</i>	1	\$ 633.70	\$ 633.70
8	SLIDING DOOR STEP PANEL GARNISH RH <i>new</i>	1	\$ 498.80	\$ 498.80
9	SLIDING DOOR WEATHERSTRIP RH <i>new</i>	1	\$ 298.00	\$ 298.00
10	SLIDING DOOR BACK INNER LOCK <i>new</i>	1	\$ 524.30	\$ 524.30
11	SLIDING DOOR LOWER ROLLER RH <i>new</i>	1	\$ 285.00	\$ 285.00
12	SLIDING DOOR LOCK CATCH RH <i>new</i>	1	\$ 78.00	\$ 78.00

Sliding Door Lower Protector 565
Delivered

TOTAL PRICE \$ 9,267.20
LESS 25% \$ 2,316.80
SUB TOTAL PRICE \$ 6,950.40

3664.30
2748.12

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	SLIDING DOOR INNER TRIM CLIP RH (SET) <i>new</i>	1	\$ 60.00	\$ 60.00
2	STEP PANEL GARNISH CLIP <i>new</i>	1	\$ 60.00	\$ 60.00
3	DOOR CHROME MOULDING (SPECIAL TYPE) <i>new</i>	1	\$ 800.00	\$ 800.00
4	DOOR VISOR (SET) <i>new</i>	1	\$ 300.00	\$ 300.00
5	DOOR STICKER 'AUTO DOOR' (SPECIAL TYPE) <i>new</i>	1	\$ 100.00	\$ 100.00

290

TO : CHINA TAIPING MOTOR CLAIM
 VEHICLE NO : SNQ3146M
 MODEL : TOYOTA VOXY HYBRID
 DATE OF ACCIDENT : 22.08.2024
 TIME OF ACCIDENT : 11:22 HOURS

TOTAL \$ 1,320.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 1,800.00	250
2	TO SPRAY PAINT AFFECTED AREA	\$ 800.00	350
3	TUFF COAT	\$ 250.00	+
4	WIRING CHECK	\$ 150.00	30
5	TRANSFER SLIDING DOOR MECHANISM RH	\$ 80.00	40
6	REMOVE AND REFIX AND RESET SLIDING DOOR AUTO SYSTEM	\$ 350.00	+
7	REMOVE & REINSTALL REAR WINDOW GLASS	\$ 60.00	40
8	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	+

TOTAL \$3,670.00

TOTAL PARTS COST : \$ 8,270.40
 TOTAL LABOUR COST : \$ 3,670.00
 TOTAL REPAIR COST : \$ 11,940.40

Admin C
 r/s 04/09/24
 03 days

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR

IRENE

HP : 8297 9787

LKK Auto Consultants hence notify
 Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 3748.22

u/s: 3K
 3K