

Borneo Motors



Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no: 6831 1188

ESTIMATE

Account Details		Account No.	Customer Details					
MS First Capital Insurance Ltd 16 Raffles Quay #42-01 Hong Leong Building Singapore 048581 Attn: Motor Claims Dept		S1000005 / ICFC1	M/S Grab Rentals Pte. Ltd 3 Media Close #01-03/06 Singapore 138498 Work: 65703925					
		Document No.						
		0						
		Document Date						
		06/09/2024						
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks	
2023	MXPL10R	MWXNB S1	05/09/2023	SNM2258B	0	32825	67/TP/SNM2258B	
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On	
JTDBBBA390L000648		M15AY699628	60	Sam San Joi	--/--/----		0.00 --/--/---- 0.00	
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount
1	Z	BP-GRAB-DS SUNDRIES - FLASH ARRIVE: DD/MM/YY 0000HR TP- ACC DATE:05/09/2024 TOW IN:05/09/2024 DATE-IN: DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORISED ON:						50 100.00
2	B	BP-LAB2 CHECK LIGHTING & WIRING SYSTEM						198.00
3	Z	BP-SLANT SUPPLY SEALANT (NETT)						300.00
4	B	BP-LAB2 TRANSFER & INSTALL COMPONENTS TO NEW DOO RS						356 792.00
5	B	BP-LAB2 REMOVE & INSTALL SEAT,CARPET,GARNISH AND TRIMMING TO ASSIST REPAIR						792.00
6	B	BP-MECH2 REPLACE SPORT RIMS AND TYRES						198.00
7	B	BP-MECH2 REPLACE & INSTALL RH FRT SUSPENSION SYST EM						792.00
8	B	BP-MECH2 REPLACE & INSTALL REAR SUSPENSION SYSTEM						1584.00
9	B	BP-MECH2 REMOVE & INSTALL ROOF LINING ASSY						1584.00
10	B	BP-MECH2 REPLACE & INSTALL AIRBAG,AIRBAG SENSORS SEAT BETLS AND ECU						2376.00
11	S	BP-SUBLET REPLACE & INSTALL FRT RH SEAT LEATHER						520.00
For & on behalf of		Customer's Signature		Charge Summary		Total		
Borneo Motors (Singapore) Pte Ltd		Please acknowledge receipt of vehicle		Parts Labour Sublet Lubrication/Fluid Others		Less Amount Due		

Customer Copy

Borneo Motors



TOYOTA

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no. 6631 1188

ESTIMATE

Account Details	Account No.	Customer Details
MS First Capital Insurance Ltd 16 Raffles Quay #42-01 Hong Leong Building Singapore 048581 Attn: Motor Claims Dept	S1000005 / ICFC1	M/S Grab Rentals Pte. Ltd
	Document No. 0	3 Media Close #01-03/06 Singapore 138498
	Document Date 06/09/2024	Work: 65703925

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2023	MXPL10R	MWXNB S1	05/09/2023	SNM2258B	0	32825	67/TP/SNM2258B

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JTDBBBA390L000648	M15AY699628	60	Sam San Joi	--/--/----	0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
12	B	BP-MECH2 CONDUCT FULL WHEEL ALIGNMENT				198.00
13	S	BP-SUBLET RH TYRES - FRT & REAR <i>20%</i>				760.00
14	B	BP-ECU2 TO RESET ECU AND REPROGRAMME				198.00
15	B	BP-LAB2 REPLACE RH ACCIDENT DAMAGED PARTS STRAIGHTEN & ALIGN RH ACCIDENT AFFECTED AREAS				7920.00
16	B	BP-RES2 RESPRAY JOB ON RH ACCIDENT AFFECTED AREA S				5904.00
17	1	U52119-5C968 COVER, FR BUMPER <i>cm</i>	1.00	500.20		500.20
18	2	U52535-52240 RETAINER, FR BUMPER <i>xm</i>	1.00	105.90		105.90
19	3	U52112-52200 EXTENSION, FR <i>sea</i>	1.00	154.40		154.40
20	4	T53879-33030 RETAINER, FR FENDER <i>xm</i>	2.00	17.00		34.00
21	5	L47749-30030 CLIP, PIN HOLD <i>me</i>	2.00	1.90		3.80
22	6	U75392-52030 RETAINER, OUTSIDE <i>xm</i>	10.00	1.80		18.00
23	7	U53811-52620 PANEL, FR FENDER, RH <i>repair</i>	1.00	985.80		985.80
24	8	T53866-52210 SEAL, FR FENDER TO <i>xm</i>	1.00	54.50		54.50
25	9	T53851-52270 PAD, FR WHEEL <i>fan</i>	1.00	71.80		71.80
26	0	U90467-07220 CLIP <i>m</i>	10.00	3.60		36.00
27	1	U53101-52B50 GRILLE SUB-ASSY, <i>cm</i>	1.00	1208.30		1208.30
28	2	T67001-52640 PANEL SUB-ASSY, FR <i>repair</i>	1.00	1921.10		1921.10
29	3	T75921-52180 TAPE, BLACK OUT, <i>xm</i>	1.00	76.40		76.40

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less Amount Due

Customer Copy

Borneo Motors



Inchcape
Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no. 6631 1188

ESTIMATE

Account Details			Account No.		Customer Details		
MS First Capital Insurance Ltd 16 Raffles Quay #42-01 Hong Leong Building Singapore 048581 Attn: Motor Claims Dept			S1000005 / ICFIC1		M/S Grab Rentals Pte. Ltd 3 Media Close #01-03/06 Singapore 138498 Work: 65703925		
			Document No.				
			0				
			Document Date				
			06/09/2024				

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2023	MXPL10R	MWXNB S1	05/09/2023	SNM2258B	0	32825	67/TP/SNM2258B

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JTDBBBA390L000648	M15AY699628	60	Sam San Joi	--/--/----	0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
30	4	T67861-52390 WEATHERSTRIP, FR <i>fan</i>	1.00	335.00		335.00
31	5	T67003-52610 PANEL SUB-ASSY, RR <i>h</i>	1.00	1966.10		✓1966.10
32	6	T75923-52170 TAPE, BLACK OUT. <i>na</i>	1.00	76.40		✓76.40
33	7	U67865-52010 WEATHERSTRIP, CTR <i>fan</i>	1.00	186.70		✓186.70
34	8	T61601-52770 PANEL SUB-ASSY, <i>h</i>	1.00	833.00		✓833.00
35	9	T61605-52140 PANEL SUB-ASSY, QTR <i>fan</i>	1.00	356.10		✓356.10
36	0	U62930-52010 DUCT ASSY, QUARTER <i>fan</i>	1.00	59.70		✓59.70
37	1	T62710-52330 WINDOW ASSY. <i>na</i>	1.00	495.80		✓495.80
38	2	T08826-08115 PANEL BONDING ADH. <i>na</i>	1.00	267.20		✓267.20
39	3	T21000-20 SIKA 182010 SIKA TACK GO! (BLA <i>na</i>	1.00	108.00		✓108.00
40	4	T21000-22 SIKA 207. G+P ADHESIVE PRIMER <i>na</i>	1.00	200.00		✓200.00
41	5	T52159-5C916 COVER, RR BUMPER <i>na</i>	1.00	516.40		✓516.40
42	6	T52161-52210 EXTENSION, RR BUMPER <i>fan</i>	1.00	179.60		✓179.60
43	7	K52161-0K040 PIECE, RR BUMPER <i>na</i>	10.00	5.80		✓58.00
44	8	T64730-52680 CO PANEL ASSY, DECK <i>fan</i>	1.00	825.10		✓825.10
45	9	U90269-04051 RIVET <i>na</i>	8.00	2.20		✓17.60
46	0	U81105-52P00 HOUSING SUB-ASSY. (Houslarp) <i>na</i>	1.00	2702.70		✓2702.70
47	1	U42611-52D30 WHEEL, DISC <i>na</i>	2.00	546.50		✓1093.00
48	2	U42602-52730 CAP SUB-ASSY, WHEEL <i>na</i>	2.00	294.40		✓588.80
49	3	T48820-K0020 LINK ASSY, FR <i>fan</i>	1.00	296.20		✓296.20

For & on behalf of Borneo Motors (Singapore) Pte Ltd	Customer's Signature	Charge Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	
			Less
			Amount Due

Borneo Motors



Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no. 6631 1188

ESTIMATE

Account Details			Account No.		Customer Details		
MS First Capital Insurance Ltd 16 Raffles Quay #42-01 Hong Leong Building Singapore 048581 Attn: Motor Claims Dept			S1000005 / ICFIC1		M/S Grab Rentals Pte. Ltd 3 Media Close #01-03/06 Singapore 138498 Work: 65703925		
			Document No. 0				
			Document Date 06/09/2024				
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2023	MXPL10R	MWXNB S1	05/09/2023	SNM2258B	0	32825	67/TP/SNM2258B
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On
JTDBBBA390L000648		M15AY699628	60	Sam San Joi	--/--/----		0.00 --/--/---- 0.00
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
50	4	T48510-52T51 ABSORBER ASSY <i>7 x an</i>	1.00	649.00		649.00	
51	5	T48068-52230 ARM SUB-ASSY, <i>2 x an</i>	1.00	1069.70		1069.70	
52	6	T43211-K0010 KNUCKLE, STEERING, <i>2 x an</i>	1.00	733.00		733.00	
53	7	T43550-52020 HUB & BEARING ASSY, <i>2 x an</i>	1.00	687.80		687.80	
54	8	T43410-52460 SHAFT ASSY, FR <i>1 x an</i>	1.00	1770.40		1770.40	
55	9	T45046-K9015 END SUB-ASSY, TIE <i>1 x an</i>	1.00	249.10		249.10	
56	0	T48530-52Q90 ABSORBER ASSY, <i>2 x an</i>	1.00	317.20		317.20	
57	1	U42110-52360 BEAM ASSY, RR AXLE <i>1 x an</i>	1.00	4015.30		4015.30	
58	2	T42450-52170 HUB & BRG ASSY, RR <i>2 x an</i>	1.00	1007.80		1007.80	
59	3	U63310-52N80 B0 HEADLINING ASSY, <i>1 x an</i>	1.00	3552.30		3552.30	
60	4	U90467-05164 B0 CLIP <i>1 x an</i>	5.00	3.10		15.50	
61	5	U62170-52220 AIR BAG ASSY, <i>1 x an</i>	1.00	2446.30		2446.30	
62	6	T71551-52G20 PAD, FR SEAT BACK, <i>1 x an</i>	1.00	482.80		482.80	
63	7	T71073-5CN01 C0 COVER SUB-ASSY, FR <i>1 x an</i>	1.00	1149.20		1149.20	
64	8	U73220-52B00 C0 BELT ASSY, FR SEAT, <i>1 x an</i>	1.00	1410.70		1410.70	
65	9	U73210-52A70 C0 BELT ASSY, FR SEAT, <i>1 x an</i>	1.00	1410.70		1410.70	
66	0	U73370-52560 C0 BELT ASSY, RR NO.1 <i>1 x an</i>	1.00	1401.80		1401.80	
67	1	U73360-52560 C0 BELT ASSY, RR NO.1 <i>1 x an</i>	1.00	1401.80		1401.80	
68	2	U89173-59415 SENSOR, AIR BAG, FR <i>1 x an</i>	1.00	472.80		472.80	
69	3	U89170-48F40 SENSOR ASSY, AIR BAG <i>1 x an</i>	1.00	1668.40		1668.40	
For & on behalf of Borneo Motors (Singapore) Pte Ltd			Customer's Signature		Charge Summary		Total
			Please acknowledge receipt of vehicle		Parts Labour Sublet Lubrication/Fluid Others		Less Amount Due

Customer Copy

Borneo Motors



TOYOTA

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-8
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188

ESTIMATE

Account Details			Account No.		Customer Details			
MS First Capital Insurance Ltd 16 Raffles Quay #42-01 Hong Leong Building Singapore 048581 Attn: Motor Claims Dept			S1000005 / ICFC1		M/S Grab Rentals Pte. Ltd 3 Media Close #01-03/06 Singapore 138498 Work: 65703925			
			Document No.					
			0					
			Document Date					
			06/09/2024					
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks	
2023	MXPL10R	MWXNB S1	05/09/2023	SNM2258B	0	32825	67/TP/SNM2258B	
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On	
JTDBBBA390L000648		M15AY699628	60	Sam San Joi	--/--/----		0.00 --/--/---- 0.00	
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount
70	4	U8983A-52020 SENSOR, PRESSURE 7-X17			1.00	384.60		384.60
LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date: <i>Rahul</i> <i>Hp 90010068</i> <i>22 days + 04 = 26 days</i> <i>09/09/24</i> <i>Reg by paint</i>								
For & on behalf of		Customer's Signature		Charge Summary		Total		
Borneo Motors (Singapore) Pte Ltd						66,843.80		
		Please acknowledge receipt of vehicle				GST 9.00% 6,015.94		
				Parts 42,627.80				
				Labour 22,936.00				
				Sublet 1,280.00				
				Lubrication/Fluid 0.00		Less 0.00		
				Others 0.00		Amount Due 72,859.74		