



Borneo Motors

chcape

o. Reg No. : 196700086Z
ST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details		Account No.	Customer Details				
MS First Capital Insurance Ltd 16 Raffles Quay #42-01 Hong Leong Building Singapore 048581 Attn: Motor Claims Dept		S1000005 / ICFIC1	M/S Grab Rentals Pte. Ltd				
		Document No. 0	3 Media Close #01-03/06 Singapore 138498				
		Document Date 06/09/2024	Work: 65703925				
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2023	MXPL10R	MWXNB S1	05/09/2023	SNM2258B	0	32825	67/TP/SNM2258B
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On
JTDBBBA390L000648		M15AY699628	60	Sam San Joi	--/--/----		0.00 --/--/---- 0.00
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
1	Z	BP-GRAB-DS SUNDRIES - FLASH ARRIVE: DD/MM/YY 0000HR TP- ACC DATE:05/09/2024 TOW IN:05/09/2024 DATE-IN: DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORISED ON:				50	100.00
2	B	BP-LAB2 CHECK LIGHTING & WIRING SYSTEM				200	198.00
3	Z	BP-SLANT SUPPLY SEALANT (NETT)				356	300.00
4	B	BP-LAB2 TRANSFER & INSTALL COMPONENTS TO NEW DOOR RS					792.00
5	B	BP-LAB2 REMOVE & INSTALL SEAT,CARPET,GARNISH AND TRIMMING TO ASSIST REPAIR					792.00
6	B	BP-MECH2 REPLACE SPORT RIMS AND TYRES					198.00
7	B	BP-MECH2 REPLACE & INSTALL RH FRT SUSPENSION SYST EM					792.00
8	B	BP-MECH2 REPLACE & INSTALL REAR SUSPENSION SYSTEM					1584.00
9	B	BP-MECH2 REMOVE & INSTALL ROOF LINING ASSY					1584.00
10	B	BP-MECH2 REPLACE & INSTALL AIRBAG,AIRBAG SENSORS SEAT BETLS AND ECU					2376.00
11	S	BP-SUBLET REPLACE & INSTALL FRT RH SEAT LEATHER					520.00
For & on behalf of		Customer's Signature	Charge Summary		Total		
Borneo Motors (Singapore) Pte Ltd		Please acknowledge receipt of vehicle	Parts		Less		
			Labour				
			Sublet		Amount Due		
			Lubrication/Fluid				
			Others				

Customer Copy



Borneo Motors



TOYOTA

chcape
Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188

ESTIMATE

Account Details			Account No.		Customer Details		
MS First Capital Insurance Ltd 16 Raffles Quay #42-01 Hong Leong Building Singapore 048581 Attn: Motor Claims Dept			S1000005 / ICFIC1		M/S Grab Rentals Pte. Ltd 3 Media Close #01-03/06 Singapore 138498 Work: 65703925		
			Document No.				
			0				
			Document Date				
			06/09/2024				
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2023	MXPL10R	MWXNB S1	05/09/2023	SNM2258B	0	32825	67/TP/SNM2258B
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On
JTDBBBA390L000648		M15AY699628	60	Sam San Joi	--/--/----		0.00 --/--/---- 0.00
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
12	B	BP-MECH2 CONDUCT FULL WHEEL ALIGNMENT				198.00	
13	S	BP-SUBLET RH TYRES - FRT & REAR <i>20%</i>				532 760.00	
14	B	BP-ECU2 TO RESET ECU AND REPROGRAMME				198.00	
15	B	BP-LAB2 REPLACE RH ACCIDENT DAMAGED PARTS				5544 7920.00	
16	B	BP-RES2 STRAIGHTEN & ALIGN RH ACCIDENT AFFECTED AREAS				4592 5904.00	
17	1	U52119-5C968 COVER, FR BUMPER <i>cm</i>	1.00	500.20		500.20	
18	2	U52535-52240 RETAINER, FR BUMPER <i>X</i>	1.00	105.90		105.90	
19	3	U52112-52200 EXTENSION, FR <i>see</i>	1.00	154.40		154.40	
20	4	T53879-33030 RETAINER, FR FENDER <i>X</i>	2.00	17.00		34.00	
21	5	L47749-30030 CLIP, PIN HOLD <i>me</i>	2.00	1.90		3.80	
22	6	U75392-52030 RETAINER, OUTSIDE <i>X</i>	10.00	1.80		18.00	
23	7	U53811-52620 PANEL, FR FENDER, RH <i>repair</i>	1.00	985.80		985.80	
24	8	T53866-52210 SEAL, FR FENDER TO <i>X</i>	1.00	54.50		54.50	
25	9	T53851-52270 PAD, FR WHEEL <i>?</i>	1.00	71.80		71.80	
26	0	U90467-07220 CLIP <i>m</i>	10.00	3.60		36.00	
27	1	U53101-52B50 GRILLE SUB-ASSY, <i>cm</i>	1.00	1208.30		1208.30	
28	2	T67001-52640 PANEL SUB-ASSY, FR <i>repair</i>	1.00	1921.10		1921.10	
29	3	T75921-52180 TAPE, BLACK OUT, <i>X</i>	1.00	76.40		76.40	
For & on behalf of			Customer's Signature		Charge Summary		Total
Borneo Motors (Singapore) Pte Ltd							
			Please acknowledge receipt of vehicle		Parts Labour Sublet Lubrication/Fluid Others		Less
							Amount Due



Borneo Motors



TOYOTA

inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188

ESTIMATE

Account Details		Account No.	Customer Details	
MS First Capital Insurance Ltd 16 Raffles Quay #42-01 Hong Leong Building Singapore 048581 Attn: Motor Claims Dept		S1000005 / ICFIC1	M/S Grab Rentals Pte. Ltd 3 Media Close #01-03/06 Singapore 138498 Work: 65703925	
		Document No. 0		
		Document Date 06/09/2024		

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2023	MXPL10R	MWXNB S1	05/09/2023	SNM2258B	0	32825	67/TP/SNM2258B

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JTDBBBA390L000648	M15AY699628	60	Sam San Joi	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
30	4	T67861-52390 WEATHERSTRIP, FR	1.00	335.00		335.00
31	5	T67003-52610 PANEL SUB-ASSY, RR	1.00	1966.10		1966.10
32	6	T75923-52170 TAPE, BLACK OUT	1.00	76.40		76.40
33	7	U67865-52010 WEATHERSTRIP, CTR	1.00	186.70		186.70
34	8	T61601-52770 PANEL SUB-ASSY, ST	1.00	833.00		833.00
35	9	T61605-52140 PANEL SUB-ASSY, QTR	1.00	356.10		356.10
36	0	U62930-52010 DUCT ASSY, QUARTER	1.00	59.70		59.70
37	1	T62710-52330 WINDOW ASSY	1.00	495.80		495.80
38	2	T08826-08115 PANEL BONDING ADH	1.00	267.20		267.20
39	3	T21000-20 SIKA 182010 SIKA TACK GO! (BLA	1.00	108.00		108.00
40	4	T21000-22 SIKA 207. G+P ADHESIVE PRIMER	1.00	200.00		200.00
41	5	T52159-5C916 COVER, RR BUMPER	1.00	516.40		516.40
42	6	T52161-52210 EXTENSION, RR BUMPER	1.00	179.60		179.60
43	7	K52161-0K040 PIECE, RR BUMPER	10.00	5.80		58.00
44	8	T64730-52680 CO PANEL ASSY, DECK	1.00	825.10		825.10
45	9	U90269-04051 RIVET	8.00	2.20		17.60
46	0	U81105-52P00 HOUSING SUB-ASSY, (Houslamp)	1.00	2702.70		2702.70
47	1	U42611-52D30 WHEEL, DISC	2.00	546.50		1093.00
48	2	U42602-52730 CAP SUB-ASSY, WHEEL	2.00	294.40		588.80
49	3	T48820-K0020 LINK ASSY, FR	1.00	296.20		296.20

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd			
	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less Amount Due



Borneo Motors



TOYOTA

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188

ESTIMATE

Account Details		Account No.	Customer Details	
MS First Capital Insurance Ltd 16 Raffles Quay #42-01 Hong Leong Building Singapore 048581 Attn: Motor Claims Dept		S1000005 / ICFIC1	M/S Grab Rentals Pte. Ltd	
		Document No. 0	3 Media Close #01-03/06 Singapore 138498	
		Document Date 06/09/2024	Work: 65703925	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2023	MXPL10R	MWXNB S1	05/09/2023	SNM2258B	0	32825	67/TP/SNM2258B

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JTDBBBA390L000648	M15AY699628	60	Sam San Joi	--/--/----	0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
50	4	T48510-52T51 ABSORBER ASSY, ?	1.00	649.00		649.00
51	5	T48068-52230 ARM SUB-ASSY, ?	1.00	1069.70		1069.70
52	6	T43211-K0010 KNUCKLE, STEERING, ?	1.00	733.00		733.00
53	7	T43550-52020 HUB & BEARING ASSY, ?	1.00	687.80		687.80
54	8	T43410-52460 SHAFT ASSY, FR ?	1.00	1770.40		1770.40
55	9	T45046-K9015 END SUB-ASSY, TIE ?	1.00	249.10		249.10
56	0	T48530-52Q90 ABSORBER ASSY, ?	1.00	317.20		317.20
57	1	U42110-52360 BEAM ASSY, RR AXLE ?	1.00	4015.30		4015.30
58	2	T42450-52170 HUB & BRG ASSY, RR ?	1.00	1007.80		1007.80
59	3	U63310-52N80 B0 HEADLINING ASSY, TURN /	1.00	3552.30		3552.30
60	4	U90467-05164 B0 CLIP /	5.00	3.10		15.50
61	5	U62170-52220 AIR BAG ASSY, ACT /	1.00	2446.30		2446.30
62	6	T71551-52G20 PAD, FR SEAT BACK, OUT /	1.00	482.80		482.80
63	7	T71073-5CN01 C0 COVER SUB-ASSY, FR ACT /	1.00	1149.20		1149.20
64	8	U73220-52B00 C0 BELT ASSY, FR SEAT, ACT /	1.00	1410.70		1410.70
65	9	U73210-52A70 C0 BELT ASSY, FR SEAT, ACT /	1.00	1410.70		1410.70
66	0	U73370-52560 C0 BELT ASSY, RR NO.1 ACT /	1.00	1401.80		1401.80
67	1	U73360-52560 C0 BELT ASSY, RR NO.1 ACT /	1.00	1401.80		1401.80
68	2	U89173-59415 SENSOR, AIR BAG, FR ACT /	1.00	472.80		472.80
69	3	U89170-48F40 SENSOR ASSY, AIR BAG ACT /	1.00	1668.40		1668.40

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd			
	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less Amount Due



Borneo Motors



TOYOTA

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188

ESTIMATE

Account Details			Account No.		Customer Details			
MS First Capital Insurance Ltd 16 Raffles Quay #42-01 Hong Leong Building Singapore 048581 Attn: Motor Claims Dept			S1000005 / ICFIC1		M/S Grab Rentals Pte. Ltd 3 Media Close #01-03/06 Singapore 138498 Work: 65703925			
			Document No. 0					
			Document Date 06/09/2024					
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks	
2023	MXPL10R	MWXNB S1	05/09/2023	SNM2258B	0	32825	67/TP/SNM2258B	
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On	
JTDBBBA390L000648		M15AY699628	60	Sam San Joi	--/--/----		0.00 --/--/---- 0.00	
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount
70	4	U8983A-52020 SENSOR, PRESSURE 7.			1.00	384.60		384.60
LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: _____ Date: _____ <i>Ram</i> <i>Hp 90010068</i> <i>22 days</i> <i>09/09/24</i> <i>Reg by paint</i>								
For & on behalf of		Customer's Signature		Charge Summary		Total		
Borneo Motors (Singapore) Pte Ltd		Please acknowledge receipt of vehicle				66,843.80		
				Parts 42,627.80		GST 9.00% 6,015.94		
				Labour 22,936.00				
				Sublet 1,280.00				
				Lubrication/Fluid 0.00		Less 0.00		
				Others 0.00		Amount Due 72,859.74		

Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Owner ID:

Vehicle Details

Vehicle No.:

Vehicle to be Exported:

Intended Deregistration Date:

Vehicle Make:

Vehicle Model:

Primary Colour:

Manufacturing Year:

Engine No.:

Chassis No.:

Maximum Power Output:

Open Market Value:

Original Registration Date:

First Registration Date:

Transfer Count:

Actual ARF Paid:

Intended PARF Rebate Details

PARF Eligibility:

PARF Eligibility Expiry Date:

PARF Rebate Amount:

Intended COE Rebate Details

COE Expiry Date:

COE Category:

COE Period(Years):

QP Paid:

COE Rebate Amount:

Total Rebate Amount:

Message

You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE.

The information contained herein is correct as at 05 Sep 2024

OK



Toyota Sienta Hybrid 1.5A

\$146,800 Instalment \$1,231/mth

PREMIUM AD

Shortlist

Loan Calculator

TRENDING NOW

mycarforum

A New Chapter - Skoda
Singapore

Overview Financial Leasing Photo Research

Depreciation

i \$15,710 / year

Reg. Date

13-Jul-2023

(8yrs 10mths 3days COE left)

Manufactured

i 2023

Mileage

32,740 km (28.2k / year)

Transmission

Auto

Engine Cap

1,490 cc

Road Tax

i \$680 / year

Power

85.0 kW (113 bhp)

View specs of the [Toyota Sienta Hybrid](#)

Curb Weight

i 1,370 kg

Fuel Type

Petrol-Electric

COE

i \$103,721

OMV

i \$27,707

ARF

i \$15,790