



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS UNITED OVERSEAS INSURANCE LTD 146 ROBINSON ROAD #02-01 UOI BUILDING SINGAPORE 068909	Ref: CS/UOI24090150/Rvp3e2 Date: 31/12/2024 Code: UOI2
---	--

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJK 80S	Veh. Inspected	SLC 7430M
Policy No.	-	Coverage	0
Claim No.	M12D00072408	Excess	\$0.00
Assign From	JOEY TAY	Assign Date	09/09/2024

2. Vehicle Details

Make & Model	MERCEDES BENZ E250 SEDAN EDITION E	C.C	1991
Engine No.	27492030571838	Year of Reg.	25/05/2016
Chassis No.	WDD2120362B305829	Colour	GREY
Odometer	136965 KM	Steering	IN ORDER
Brakes	IN ORDER	General	FAIR
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	245/40Z R18	MICHELIN	6
L/H Front Tyre	245/40Z R18	MICHELIN	6
R/H Rear Tyre	245/40Z R18	MICHELIN	6
L/H Rear Tyre	245/40Z R18	MICHELIN	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	08/08/2024	Inspection Date	24/09/2024
Survey held at	CYCLE & CARRIAGE INDUSTRIES PL 188 PANDAN LOOP SINGAPORE 128378 (MERCEDES-BENZ)		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days