

 $51~\mathrm{UBI~AVE~1,\#01-25~PAYA~UBI~INDUSTRIAL~PARK, SINGAPORE~408933~TEL: (065)~62563561~FAX: (065)~6256431};$

Preliminary Advice

To: Liberty Insurance Pte Ltd Date: 18/09/2024

BVS24/0642 - SMP 8543J

Survey details

Date of loss	5/9/2024
Date of Assignment	10/9/2024
Date of survey	10/9/2024
Location of survey	AUTOBACS CAR CARE (S) PTE LTD

Vehicle Details:

Claim Type:	THIRD PARTY
Vehicle Number	SMP 8543J
Make and Model	SUBARU IMPREZA 5D (A)
Vehicle Type	HATCHBACK
Date of Registration	18 Oct 2019
Vehicle Colour	SILVER
Market Value (Est)	\$70,000.00
LTA Rebate	\$31,324.00
Nett Value	\$38,676.00

Proposed/Revised repair cost:

Workshop Estimate	\$5,810.00
Revised Estimate	\$2,500.00 (Lump sum)
"Check" Items	\$0.00
Total	\$2,500.00 (Lump sum)
Number of days of repair (Est)	5 days

Remarks:	The vehicle sustained damages at the o/s rear portion.
	Damages Consistent.
	Please note that the preliminary advise amount (Revised) stated are subject to consistency check, part prices and labour cost.
	Habour cost.