

EROFIA MOTOR TRADING PTE LTD (201202259N)

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

E-Mail: erofia@singnet.com.sg

CHWA

Name : Lim Meng Wah (81212187)

Accident Date : 01-Sep-24

Vehicle No : FBP8354T (COE:19062029)

Vehicle Model : Sym Joyride S
200I ABS

Estimated Repair Costs

Qty	Description List Items	Amount S(\$)
1	Front fairing	580.00 ✓
1	Front fairing inner panel	495.00 ✓
1	Front lower fairing	350.00 ✓
1	Front fork assy	850.00 ✓
1	Fork under bracket	350.00 ✓
1	Front mudguard	275.00 ✓
1	Headlamp	980.00 ✓
1	Front signal	245.00 ✓
1	Windshield	480.00 ✓
1	Meter cover (matt)	285.00 ✓
1	Footstep panel	355.00 ✓
1	FootStep Lower Panel (1 Set)	480.00 ✓
1	Side mirrors	250.00 ✓
1	Handle-bar	380.00 X
1	Handle-bar end	180.00 ✓
1	Hand grip	120.00 X
1	Brake levers	168.00 ✓
2	Rear fairing - R/L/H	580.00 ✓
1	Rear Footrest	220.00 ✓
1	Exhaust assy	950.00 ✓
1	Exhaust protector	220.00 ✓
1	Exhaust end cap	155.00 X
		\$ 8,948.00
		Less 10% \$ 894.80
		\$ 8,053.20

1 Radiator

8400 CNO ✓

Special Net Items

EROFIA MOTOR TRADING PTE LTD (201202259N)

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

E-Mail: erofia@singnet.com.sg

Name : Lim Meng Wah (81212187)

Accident Date : 01-Sep-24

Vehicle No : FBP8354T (COE:19062029)

Vehicle Model : Sym Joyride S
200I ABS

Estimated Repair Costs

1	Number plate (1 set)	1 set	\$	38.00	10
2	Fork oils	11	\$	30.00	X
2	Fork oil seals	11	\$	56.00	X
1	Steering cone (1 set)	1 set	\$	150.00	80
1	Logo	1 set	\$	165.00	60
1	Rear box	1 set	\$	580.00	280
1	Rear box bracket	1	\$	180.00	X
				\$	1,199.00

S/No. Labour

1	To provide towing service (LOD) S\$70.00	refer LOD	\$	-	X
2	To check wiring and reset headlamp focusing		\$	11 80.00	X
3	To repair body frame		\$	11 480.00	X
4	To spray painting		\$	800.00	380
5	To provide labour		\$	480.00	300
				\$	1,840.00

Grand Total

\$ 11,092.20

Singapore Dollars: Eleven Thousand Ninety-Two and Cents: Twenty only



EROFIA MOTOR TRADING PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

9-6925
10
6232.50
430
680
7342.50
22
5874