



Letter of Claims

Request of direct settlement.

We are submitting a claim on behalf of our customer LAU HUAN GUAN JAMES

NRIC 84886 insured of vehicle SNE 84886 against

your insured vehicle number SH 8813B. (MS First Capital)

On the accident dated on 18/06/2024 (ddmmyyyy) along

ALONG BEDOK NORTH STREET 1

Dated this 19 (day) of 06 (month) 20 24.



Volkswagen Group Singapore

247 Alexandra Road

Singapore 159934

DID: 6305 7216

HP: 8121 4681

meiy.wong@vw.com.sg

VOLKSWAGEN

247 Alexandra Road
Singapore 159934
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Quotation

Non binding - Preview

Page 1/2

Company
Ms First Capital Insurance
Limited
6 RAFFLES QUAY
#21-00
Singapore 048580

Customer Details:
Mr
LAU
HUAN GUAN JAMES
(LIU HUANYUAN)
16 BEDOK NORTH DRIVE
#10-03
SINGAPORE 465494

Document no.
Document date 19-06-2024
Customer no. 6151041856
Customer GST-ID 195000106C
Dealer 30001
Job order number 2024016352/ 1
Job order date 18-06-2024
Service Advisor YEN MEI WONG

License plate	Model code	First registration	VIN	Model	Mileage
SNE8488G	CD13LML0	12-01-2022	WVWZZZCDZNW119477	Golf 1.5 Life GT110eTSID7F	30,478

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount Incl. GST
9801B004	B&P CHECK SHORT CIRCUIT / HARNESS REPAIR				#8	280.00	305.20
9801B005	B&P DIAGNOSIS AND PROGRAMMING				#8	480.00	523.20
5H6807417P GRU	Cover For Bumper Primed	1	pcs.	1,489.08	#8	1,489.08	1,623.10
5H0919492	Sensor Bracket	1	pcs.	15.10	#8	15.10	16.46
5H0919491A	Sensor Bracket	2	pcs.	15.10	#8	30.20	32.92
5H0919491	Sensor Bracket	1	pcs.	15.10	#8	15.10	16.46
5WA919275B GRU	Sensor Primed	1	pcs.	206.04	#8	206.04	224.58
3Q0919133 9B9	Seal Ring Satin Black	1	pcs.	6.58	#8	6.58	7.17
D 822150A1	Bonding Agent For Plastic	1	pcs.	78.24	#8	78.24	85.28
D 180KU2A1	2k-Plastic Adhesive	1	pcs.	94.98	#8	94.98	103.53
5H6807568 9B9	Rear Diffuser Satin Black	1	pcs.	302.00	#8	302.00	329.18
5H6807393E	Guide Piece	1	pcs.	61.15	#8	61.15	66.65
	LHR BUMPER BRACKET (UPPER)						
5H6807394E	Guide Piece	1	pcs.	61.15	#8	61.15	66.65
	RHR BUMPER BRACKET (UPPER)						
5H6807393D	Guide Piece	1	pcs.	61.15	#8	61.15	66.65
	LHR BUMPER BRACKET (SIDE)						
5H6807394D	Guide Piece	1	pcs.	61.15	#8	61.15	66.65
	RHR BUMPER BRACKET (SIDE)						
5H0945105	Reflector	1	pcs.	89.14	#8	89.14	97.16
	LH						
	LABOUR	3	pcs.	840.00	#8	2,520.00	2,746.80
	SPRAY PAINT	3	pcs.	800.00	#8	2,400.00	2,616.00
	ALLIANZ ARF VS MS FIRST CAPITAL 3RD PARTY VEHICLE SH8813B D.O.A: 18-06-2024 SURVEY BY:						

Quotation valid till 25-06-2024

Tax Code	Labour	Material	GST %	GST	Total amount excl. GST	Total amount Incl. GST
#8	760.00	7,491.06	9%	742.60	8,251.06	8,993.66
Total	760.00	7,491.06		742.60	8,251.06	8,993.66

Customer

Service Advisor

VOLKSWAGEN

247 Alexandra Road
Singapore 159934
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Quotation
Non binding - Preview

Page	2/2
Document no.	
Document date	19-08-2024
Customer no.	6151041856
Customer GST-ID	195000106C
Dealer	30001
Job order number	2024016352/ 1
Job order date	18-08-2024
Service Advisor	YEN MEI WONG

Company	Customer Details:
Ma First Capital Insurance	Mr
Limited	LAU
6 RAFFLES QUAY	HUAN GUAN JAMES
#21-00	(LIU HUANYUAN)
Singapore 048580	16 BEDOK NORTH DRIVE
	#10-03
	SINGAPORE 465494

License plate	Model code	First registration	VIN	Model	Mileage
SNE8488G	CD13LML0	12-01-2022	WVWZZZCDZNW119477	Golf 1.5 Life GT110eTSID7F	30,478

-----VISIT OUR WEBSITE: aftersales.vw.com.sg (for online service appointments) and volkswagen.com.sg and www.skoda.com.sg (for additional services, products and promotions).-----

All invoices are denominated in SGD, unless otherwise stated.