

VOLKSWAGEN

247 Alexandra Road
Singapore 159834
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Quotation

Non binding - Preview

Page 1/2

Company
Ms First Capital Insurance
Limited
6 RAFFLES QUAY
#21-00
Singapore 048580

Customer Details:
Mr
LAU
HUAN GUAN JAMES
(LIU HUANYUAN)
16 BEDOK NORTH DRIVE
#10-03
SINGAPORE 465494

Document no.
Document date
Customer no.
Customer GST-ID
Dealer
Job order number
Job order date
Service Advisor
19-06-2024
6151041856
195000106C
30001
2024016352/ 1
18-06-2024
YEN MEI WONG

License plate	Model code	First registration	VIN	Model	Mileage
SNE8488G	CD13LML0	12-01-2022	WVWZZZCDZNW119477	Golf 1.5 Life GT110eTSID7F	30,478

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
9801B004	B&P CHECK SHORT CIRCUIT / HARNESS REPAIR				#8	280.00	305.20
9801B005	B&P DIAGNOSIS AND PROGRAMMING				#8	480.00	523.20
5H6807417P GRU	Cover For Bumper Primed <i>See</i>	1	pcs.	1,489.08	#8	1,489.08	1,623.10
5H0919492	Sensor Bracket <i>See</i>	1	pcs.	15.10	#8	15.10	16.46
5H0919491A	Sensor Bracket <i>See</i>	2	pcs.	15.10	#8	30.20	32.92
5H0919491	Sensor Bracket <i>See</i>	1	pcs.	15.10	#8	15.10	16.46
5WA919275B GRU	Sensor Primed <i>X</i>	1	pcs.	206.04	#8	206.04	224.58
3Q0919133 9B9	Seal Ring Satin Black <i>See</i>	1	pcs.	6.58	#8	6.58	7.17
D 822150A1	Bonding Agent For Plastic <i>See</i>	1	pcs.	78.24	#8	78.24	85.28
D 180KU2A1	2k-Plastic Adhesive <i>See</i>	1	pcs.	94.98	#8	94.98	103.63
5H6807568 9B9	Rear Diffuser Satin Black <i>See</i>	1	pcs.	302.00	#8	302.00	329.18
5H6807393E	Guide Piece	1	pcs.	61.15	#8	61.15	66.65
5H6807394E	LHR BUMPER BRACKET (UPPER) ? Guide Piece	1	pcs.	61.15	#8	61.15	66.65
5H6807393D	RHR BUMPER BRACKET (UPPER) X Guide Piece	1	pcs.	61.15	#8	61.15	66.65
5H6807394D	LHR BUMPER BRACKET (SIDE) ? Guide Piece	1	pcs.	61.15	#8	61.15	66.65
5H0945105	RHR BUMPER BRACKET (SIDE) X Reflector <i>??</i> LH	1	pcs.	89.14	#8	89.14	97.18
	LABOUR	1/3	pcs.	840.00	#8	840.00	908.40
	SPRAY PAINT	1/2	pcs.	800.00	#8	800.00	864.00
	ALLIANZ ARF VS MS FIRST CAPITAL 3RD PARTY VEHICLE SH8813B D.O.A: 18-06-2024 SURVEY BY:						

Quotation valid till 25-06-2024

Tax Code	Labour	Material	GST %	GST	Total amount excl. GST	Total amount incl. GST
#8	760.00	7,491.06	9%	742.60	8,251.06	8,993.66
Total	760.00	7,491.06		742.60	8,251.06	8,993.66

Customer

Service Advisor

Handwritten notes:
Kam
4p 900/10068
3 days
21/06/24
Regr 54 paint

Handwritten date:
10/06/2024

VOLKSWAGEN

247 Alexandra Road
Singapore 159934
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Quotation

Non binding - Preview

Page

2/2

Company
Ms First Capital Insurance
Limited
6 RAFFLES QUAY
#21-00
Singapore 048580

Customer Details:
Mr
LAU
HUAN GUAN JAMES
(LIU HUANYUAN)
16 BEDOK NORTH DRIVE
#10-03
SINGAPORE 465494

Document no. 19-08-2024
Document date 6151041856
Customer no. 195000106C
Customer GST-ID 30001
Dealer 2024016352/ 1
Job order number 18-06-2024
Job order date YEN MEI WONG
Service Advisor

License plate	Model code	First registration	VIN	Model	Mileage
SNE8488G	CD13LML0	12-01-2022	WWWZZZCDZNW119477	Golf 1.5 Life GT110eTSID7F	30,478

-----VISIT OUR WEBSITE: aftersales.vw.com.sg (for online service appointments) and volkswagen.com.sg and www.skoda.com.sg (for additional services, products and promotions).-----

All invoices are denominated in SGD, unless otherwise stated.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: