

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0672/2024/KS
DATE : 11-Sep-24
WIP : 30314

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 18/9/2024

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

OWNER'S NAME : MR SEAN LEE JUNN KIT
ADDRESS : 36 PENNEFATHER ROAD
SINGAPORE 424456
TELEPHONE : HP +65 90036947
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 724007167
VEHICLE NO : **SMD 539 M**
MODEL CODE : AUDI Q3 SPORTBACK 1.5 TFS
MODEL YEAR : 23/1/2024
ENGINE NO : DFY 615573
CHASSIS NO : WAUZZZF31R1018403
MILEAGE : KM
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 8-Sep-24
PLACE OF ACCIDENT : 552 SERANGOON NORTH AVE 3, BLOCK552
SINGAPORE 550552

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE. SMD 539 M.

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID.	S/N \$ 280.00 ✓	✓
2	TO DISMANTLE AND RENEW REAR BUMPER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 1,600.00 500 ✓	✓
3	TO RESPRAY REAR BUMPER AND BOTH WHEEL ARCH TRIMS.	\$ 1,800.00 1050 ✓	Wheel Arc 250 x 2 = 500 Bumper 550 1050
4	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ ✓ 292.00 ✓	✓
TOTAL LABOUR CHARGES		: \$ 3,972.00	

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMD 539 M.

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR BUMPER <i>Repair</i>	1	\$ 1,960.00	+
2	REAR BUMPER DAMPER - LH / RH <i>new</i>	2	\$ 48.00	+
3	REAR BUMPER SPOILER <i>Del'd</i>	1	\$ 573.00	✓ 458
4	REAR BUMPER GRILLE - LH <i>? nn</i>	1	\$ 573.00	? X
5	REAR BUMPER PARKING AID SUPPORT - LH <i>new</i>	1	\$ 32.00	+
6	REAR LIGHT REFLECTOR - LH <i>Crash'd</i>	1	\$ 49.00	✓ 38.72
7	REAR BUMPER ADAPTOR - LH <i>?</i>	1	\$ 107.00	+
8	REAR BUMPER BRACKET - LH <i>den</i>	1	\$ 60.00	+
9	REAR PARKING AID SENSOR <i>damaged</i>	1	\$ 286.00	✓ 228.80
10	REAR PARKING AID SENSOR SEAL RING <i>new</i> nec	4	\$ 11.00	✓ 8.64
11	REAR WHEEL ARCH COVER - LH / RH <i>new</i>	2	\$ 1,278.00	✓ 1022.40
12	SUNDRIES <i>? nec</i>		\$ 500.00	? 1.44
TOTAL SPARE PARTS		:	\$ 5,477.00	
TOTAL LABOUR CHARGES		:	\$ 3,972.00	
GRAND TOTAL		:	\$ 9,449.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME
SURVEYED DATE
AUTHORISED DATE
EXCESS COST
LIABILITY
REMARKS

: Adrian Lim
24/09/24 ✓

: Not Authorised, 03 Days

PLEASE NOTE

: THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT