

ASSIGNMENT

From: _____ Date: _____

Estimate No: _____

OD / TP RES / CD RES / EVA / INV / MV

To in _____ Vehicle No: _____

at _____

of _____

Insured: _____

Policy No: _____

Claim No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Vehicle: _____

(Policy Condition)

Remark: The vehicle had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SMD539M Yr Regn: 2024/Jan.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Andi Q3 Sportback 1498

Colour: Green A/C: Insured / Std / NI / NA

Sp. Reading: 7001 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WAU22ZF31R1018403

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / SRim STD A/Rim or

Tyre Size: F: 235/55R18

R: 235/55R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Continental

Front

Rear

R/Bal. 06 mm

R/Bal. 06 mm

L/Bal. 06 mm

L/Bal. 06 mm

D.O.A.

D.O.A. 24/09/24

Survey held at

Premium

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	OD ALG
	COE Expiry
	Estimate given during : Yes (✓) / No ()
	1st Survey
	MV : <u>110K</u>
	PV : <u>1308K</u>
	Nett : <u>79.2K</u>

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

3 + RS. \$1

Photos

Others

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Inve (\$

Report Format: _____

Report Form / P.P. / C

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0672/2024/KS
DATE : 11-Sep-24
WIP : 30314

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 18/9/2024

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

OWNER'S NAME : MR SEAN LEE JUNN KIT
ADDRESS : 36 PENNEFATHER ROAD
SINGAPORE 424456
TELEPHONE : HP +65 90036947
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 724007167
VEHICLE NO : **SMD 539 M**
MODEL CODE : AUDI Q3 SPORTBACK 1.5 TFS
MODEL YEAR : 23/1/2024
ENGINE NO : DFY 615573
CHASSIS NO : WAUZZZF31R1018403
MILEAGE : KM
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 8-Sep-24
PLACE OF ACCIDENT : 552 SERANGOON NORTH AVE 3, BLOCK552
SINGAPORE 550552

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE. SMD 539 M.

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID.	S/N \$ 280.00 ✓	
2	TO DISMANTLE AND RENEW REAR BUMPER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 1,600.00 500	
3	TO RESPRAY REAR BUMPER AND BOTH WHEEL ARCH TRIMS.	\$ 1,800.00 1050	Wheel Arc 250 x 2 = 500 Bumper 550 <u>1050</u>
4	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ ✓ 292.00	
TOTAL LABOUR CHARGES		: \$ <u>3,972.00</u>	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMD 539 M.

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR BUMPER <i>Repair</i>	1	\$ 1,960.00	+
2	REAR BUMPER DAMPER - LH / RH <i>new</i>	2	\$ 48.00	x
3	REAR BUMPER SPOILER <i>Del'd</i>	1	\$ 573.00	✓
4	REAR BUMPER GRILLE - LH <i>?</i>	1	\$ 573.00	?
5	REAR BUMPER PARKING AID SUPPORT - LH <i>new</i>	1	\$ 32.00	+
6	REAR LIGHT REFLECTOR - LH <i>Crash'd</i>	1	\$ 49.00	✓
7	REAR BUMPER ADAPTOR - LH <i>?</i>	1	\$ 107.00	+
8	REAR BUMPER BRACKET - LH <i>2 new</i>	1	\$ 60.00	+
9	REAR PARKING AID SENSOR	1	\$ 286.00	+
10	REAR PARKING AID SENSOR SEAL RING <i>new</i>	4	\$ 11.00	+
11	REAR WHEEL ARCH COVER - LH / RH <i>new</i>	2	\$ 1,278.00	✓
12	SUNDRIES <i>?</i>		\$ 500.00	?
TOTAL SPARE PARTS		:	\$ 5,477.00	
TOTAL LABOUR CHARGES		:	\$ 3,972.00	
GRAND TOTAL		:	\$ 9,449.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :

SURVEYED DATE :

AUTHORISED DATE :

EXCESS COST :

LIABILITY :

REMARKS :

Adrian King
24/09/24

Not Authorised, 03 Days

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.

FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,

PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT