

SUCCESS UNITED PTE LTD

2 Kaki Bukit Ave 2, #01-33 / #02-29
Kaki Bukit Autohub, Singapore 417921
Tel No. : 67461515 / 67471787 Fax No. : 67485015
Website : www.successunited.com.sg
Buss. Reg. No. : GST No. 200402570G

AIG Asia Pacific Insurance Pte Ltd
AIG Building
78 Shenton Way, #07-16
Singapore 079120
Attention : Motor Claim Department
Contact : 64191053 Fax No. : 68357416

Estimate : TP24-104

Date : 10/09/2024
Vehicle Num. : SGG4988D
Make/Model : Mazda CX-30-2020
Chassis/Eng# : JM6DM2W7AL0100543/PE31533516
Accident Date : 06/09/2024
Claim No. :
Reference :
Policy No. : SI24V08399/VPE/R03

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1	Frt Bumper Lower Air Grille		527.10
2.	1	Frt Bumper Side Holder RH		173.40
3.	1	Frt number plate base		215.80
List Total S\$:				916.30
20.00% Discount S\$:				183.26
				733.04
SPECIAL NETT ITEMS :				
1.	8	Frt Bumper Clips	7.60	60.80
Special Nett Total S\$:				60.80
LABOUR :				
To remove, repair and replaced damaged bodyparts, realign bodyworks & where consistent to the accident				350.00
To putty and respray painting on frt bumper and frt bumper top.				800.00
Labour Total S\$:				1,150.00
Total S\$:				1,943.84

SUCCESS UNITED PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 430
(P/P)