

SUCCESS UNITED PTE LTD

2 Kaki Bukit Ave 2, #01-33 / #02-29
Kaki Bukit Autohub, Singapore 417921
Tel No. : 67461515 / 67471787 Fax No. : 67485015
Website : www.successunited.com.sg
Buss. Reg. No. : GST No. 200402570C

AIG Asia Pacific Insurance Pte Ltd
AIG Building
78 Shenton Way, #07-16
Singapore 079120
Attention : Motor Claim Department
Contact : 64191053 Fax No. : 68357416

Estimate : TP24-104

Date : 10/09/2024
Vehicle Num. : SGG4988D
Make/Model : Mazda CX-30-2020
Chassis/Eng# : JM6DM2W7AL0100543/PE31533516
Accident Date : 06/09/2024
Claim No. :
Reference :
Policy No. : SI24V08399/VPE/R03

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

1.	1	LIST ITEMS :		
2.	1	Frt Bumper Lower Air Grille		527.10
3.	1	Frt Bumper Side Holder RH		173.40
3.	1	Frt number plate base		215.80
		List TotalS\$:		916.30
		20.00% Discount S\$:		183.26
				733.04

1.	8	SPECIAL NETT ITEMS :	7.60	60.80
		Frt Bumper Clips		60.80
		Special Nett Total S\$:		60.80
		LABOUR :		
		To remove, repair and replaced damaged bodyparts, realign bodyworks & where consistent to the accident		350.00
		To putty and respray painting on frt bumper and frt bumper top.		800.00
		Labour Total S\$:		1,150.00

Adnan Lj
P/r 10/09/24

Total S\$: 1,943.84

=====

SUCCESS UNITED PTE LTD

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: