

## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Affiliated to Federation Internatio	nale Des Experts En	Automobile
MS	INCOME INSURAN	NCE LTD	Ref:	CS/INC24090187/Anh3
	75 BRAS BASAH F		Date:	09/10/2024
	INCOME CENTRE	SINGAPORE 189557	Code:	INC
1.	Policy Particulars :- THIRD PARTY CLAIM			
	Insured Veh.	SND 5026G	Veh. Inspected	SMF 5531R
	Policy No.	-	Coverage	0
	Claim No.	MT/1294338-002	Excess	\$0.00
	Assign From	JULIE MANGUBAT	Assign Date	10/09/2024
2.		Vehic	le Details	
	Make & Model	HONDA FREED	C.C	1496
	Engine No.	L15B4463755	Year of Reg.	07/01/2022
	Chassis No.	GB51119610	Colour	GREY
	Odometer	20571 KM	Steering	IN ORDER
	Brakes	IN ORDER	General	GOOD
	Modification(s)	RIMS: SPORTS RIM		
3.	Conditions of Tyres			
		Size	Make	Balance (mm)
	R/H Front Tyre	185/65R15	YOKOHAMA	6
	L/H Front Tyre	185/65R15	YOKOHAMA	6
	R/H Rear Tyre	185/65R15	YOKOHAMA	6
	L/H Rear Tyre	185/65R15	YOKOHAMA	6
4.		•	n of Damages	
HE	VEHICLE SUSTAIN	NED DAMAGES AT THE REAR PORT	ION.	
DAN	IAGES SEE DETAIL	_S.		
5.	General Information			
	Accident Date	09/09/2024	Inspection Date	11/09/2024 (14:29)
	Survey held at	ADVANCE AUTO GARAGE 10 KAKI BUKI ROAD 2 #01-10 FIRST EAST CENTER SINGAPORE 417868		
5a. Remarks				
		AS CONDUCTED ON A"WITHOUT POYOUR INSTRUCTIONS, WE HAVE		REPAIRS.
			Days of Repair	

ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days