

# ADVANCE AUTO GARAGE

10 KAKI BUKIT ROAD 2 #01-21 FIRST EAST CENTRE  
SINGAPORE 417868  
TEL: 90079247

|               |                   |                 |             |
|---------------|-------------------|-----------------|-------------|
| TO            | : NTUC            | DATE            | : 11/9/2024 |
| VEHICLE NO    | : SMF5531R (2022) | <i>Hui Rong</i> |             |
| VEHICLE MODEL | : HONDA FREED     |                 |             |
| CHASSIS NO    | : GB51119610      |                 |             |

## CLAIM DETAILS: PARTS

|    | ITEMS                                     | QTY | UNIT PRICE  | TOTAL       |
|----|-------------------------------------------|-----|-------------|-------------|
| 1  | REAR BUMPER <i>Dehnd</i>                  | 1   | \$ 955.00   | \$ 955.00   |
| 2  | REAR BUMPER SIDE HOLDER <i>ren</i>        | 2   | \$ 83.10    | \$ 166.20   |
| 3  | REAR BUMPER INNER SIDE GARNISH <i>ren</i> | 2   | \$ 46.80    | \$ 93.60    |
| 4  | REAR END PANEL <i>Repair</i>              | 1   | \$ 655.00   | \$ 655.00   |
| 5  | REAR END PANEL TOP GARNISH <i>Dehnd</i>   | 1   | \$ 169.30   | \$ 169.30   |
| 6  | TAILLAMP <i>ren</i>                       | 2   | \$ 581.00   | \$ 1,162.00 |
| 7  | TAILGATE <i>Dehnd</i>                     | 1   | \$ 1,208.00 | \$ 1,208.00 |
| 8  | TAILGATE LOCK <i>Dehnd</i>                | 1   | \$ 186.20   | \$ 186.20   |
| 9  | TAILGATE WEATHERSTRIP <i>ren</i>          | 1   | \$ 168.50   | \$ 168.50   |
| 10 | TAILGATE OUTER CHROME GARNISH <i>ren</i>  | 1   | \$ 320.40   | \$ 320.40   |
| 11 | TAILGATE REFLECTOR <i>ren</i>             | 2   | \$ 383.50   | \$ 767.00   |
| 12 | TAILGATE INNER TRIM BOARD <i>ren</i>      | 1   | \$ 391.70   | \$ 391.70   |
| 13 | TAILGATE GLASS MOULDING <i>ren</i>        | 1   | \$ 124.60   | \$ 124.60   |
| 14 | TAILGATE INNER HANDLE <i>ren</i>          | 1   | \$ 28.00    | \$ 28.00    |
| 15 | HONDA LOGO <i>3 ren</i>                   | 1   | \$ 48.00    | \$ 48.00    |
| 16 | FREED WORDING <i>3 ren</i>                | 1   | \$ 76.40    | \$ 76.40    |
| 17 | REAR FENDER INNER TRIM BOARD <i>ren</i>   | 2   | \$ 386.10   | \$ 772.20   |
| 18 | FLOOR PANEL <i>3 ren</i>                  | 1   | \$ 1,219.50 | \$ 1,219.50 |
| 19 | FLOOR PANEL TOP MAT <i>3 ren</i>          | 1   | \$ 950.80   | \$ 950.80   |

TOTAL PRICE: \$ 9,462.40  
LESS 20% \$ 1,892.48  
SUB TOTAL PRICE: \$ 7,569.92

*315920*  
*252736*

## SPECIAL NETT ITEMS

|    | ITEMS                                           | QTY    | UNIT PRICE | TOTAL     |
|----|-------------------------------------------------|--------|------------|-----------|
| 1  | REAR NUMBER PLATE <i>3 ren</i>                  | 1      | \$ 30.00   | \$ 30.00  |
| 2  | REAR NUMBER PLATE HOLDER <i>3 ren</i>           | 1      | \$ 30.00   | \$ 30.00  |
| 3  | REAR BUMPER CLIPS <i>ren</i>                    | 1 SET  | \$ 50.00   | \$ 50.00  |
| 4  | REAR BUMPER UNDERCOVER CLIPS <i>ren</i>         | 1 SET  | \$ 50.00   | \$ 50.00  |
| 5  | REAR END PANEL TOP GARNISH CLIPS <i>ren</i>     | 1 SET  | \$ 20.00   | \$ 20.00  |
| 6  | REAR END PANEL SEALANT <i>ren</i>               | 1 SET  | \$ 80.00   | \$ 80.00  |
| 7  | REVERSE SENSOR <i>Dehnd</i>                     | 1 SET  | \$ 280.00  | \$ 280.00 |
| 8  | REAR CAMERA <i>ren</i>                          | 1      | \$ 480.00  | \$ 480.00 |
| 9  | TAILGATE OUTER CHROME GARNISH CLIPS <i>ren</i>  | 1 SET  | \$ 30.00   | \$ 30.00  |
| 10 | TAILGATE INNER TRIM BOARD CLIPS <i>3 ren</i>    | 1 SET  | \$ 50.00   | \$ 50.00  |
| 11 | TAILGATE GLASS SEALANT <i>3 ren</i>             | 1 SET  | \$ 80.00   | \$ 80.00  |
| 12 | REAR FENDER INNER TRIM BOARD CLIPS <i>3 ren</i> | 2 SETS | \$ 50.00   | \$ 100.00 |

|         |                           |       |           |           |
|---------|---------------------------|-------|-----------|-----------|
| 13      | FLOOR PANEL TOP MAT CLIPS | 1 SET | \$ 100.00 | \$ 100.00 |
| TOTAL : |                           |       | \$        | 1,380.00  |

#### LABOUR

|        | JOB                                          | PRICE       | ADJUSTED COST | APPROVED |
|--------|----------------------------------------------|-------------|---------------|----------|
| 1      | PANEL BEATING, REMOVE AND REFIT PARTS        | \$ 1,400.00 | 600           |          |
| 2      | SPRAY PAINTING TO AFFECTED AREA              | \$ 1,200.00 | 600           |          |
| 3      | WIRING CHECK                                 | \$ 50.00    | 30            |          |
| 4      | TO APPLY TUFF COAT                           | \$ 150.00   | 30            |          |
| 5      | TO REMOVE REVERSE SENSOR                     | \$ 100.00   | 50            |          |
| 6      | TO REMOVE AND REFIT UPHOLSTERY AND REAR SEAT | \$ 250.00   | 30            |          |
| 7      | TO TRANSFER TAILGATE FITTINGS                | \$ 150.00   | 60            |          |
| 8      | TO REMOVE AND REFIT TAILGATE GLASS           | \$ 180.00   | 120           |          |
| 9      | TO REMOVE AND REFIT TAILGATE CAMERA          | \$ 100.00   | 50            |          |
| 10     | TO REMOVE AND REFIT REAR VIDEO RECORDER      | \$ 100.00   | X             |          |
| TOTAL: |                                              | \$ 3,680.00 |               |          |

#### ESTIMATE REPORT

|                    |    |           |
|--------------------|----|-----------|
| TOTAL PARTS COST:  | \$ | 8,949.92  |
| TOTAL LABOUR COST: | \$ | 3,680.00  |
| TOTAL REPAIR COST: | \$ | 12,629.92 |

Total: 4437.36

H/S: 3.51K

04 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: