

MODERN AUTOMOTIVE PTE LTD
BLK 3023A UBI ROAD 1 # 01-61
SINGAPORE 408717

Tel : 6748 4422 / 6745 4422 Fax : 6747- 6720 REG NO 200501102H

SOMPO INSURANCE SINGAPORE PTE LTD

50 Raffles Place # 03-03
 Singapore Land Tower
 Singapore 048623
 Tel : 64 6329 - 5324
 Fax : 6221 - 3147

ALG.

Quotation
 DATE : 12.09.2024
 VEH NO : SMK3898U *Yan.*
 MODEL : Toyota Camry
 D O A : 07.09.2024
 YR REF : GBE8173G

Attn : Motor Claim Dept (Pls arrange vehicle survey & check liability)

RE : ESTIMATE FOR ACCIDENT REPAIR SMK3898U (TOYOTA CAMRY)

<u>Item</u>	<u>Description</u>	<u>Qty</u>	<u>Amt</u>
NO	LIST ITEMS		
1	Rear Bumper <i>behind</i>	1	994.50 ✓
2	Rear Bumper Side Holder - LH & RH <i>3 x new</i>	2	291.00 x
3	Rear Bumper Reflector - LH & RH	2	344.40 x
4	Rear Bumper Lower Garnish <i>cut</i>	1	503.90 ✓
5	Rear Bumper Sensor <i>1 piece damaged</i>	2	590.20 <i>285.10</i>
6	Rear Bumper Reinforcement <i>new</i>	1	455.70 x
7	Rear End Panel <i>Repair</i>	1	788.50 x
8	Rear End Panel Top Garnish <i>behind</i>	1	356.10 ✓
9	Taillamp - LH & RH <i>new</i>	2	1,760.20 x
10	Bootlid <i>Dented</i>	1	1,373.90 ✓
11	Bootlid Lock <i>new</i>	1	480.20 x
12	Bootlid Weatherstripe <i>new</i>	1	395.40 x
13	Toyota Logo <i>3 new</i>	1	80.60 ✓
14	Hybrid Emblem	1	60.90 ✓
			\$ 8,475.50
Less 25%			(2,118.88)
			\$ 6,356.63

S/NET ITEMS

1	Rear Bumper Clips <i>new</i>	1 set	\$ 50.00 ✓
2	Rear End Panel Top Garnish Clips <i>new</i>	1 set	\$ 20.00 ✓
3	Rear End Panel Sealant <i>new</i>	1	\$ 60.00 x
Total Parts			\$ 6,486.63

LABOUR CHARGE

1	To knocking & pull out rear portion & renew above parts	\$	1,000.00	500
2	To putty & spray up paint works	\$	1,000.00	600
3	To check wiring	\$	50.00	30
4	To apply tuff coat	\$	100.00	40
5	To remove upholstery	\$	150.00	30
6	To remove reverse sensor	\$	100.00	50
7	To remove rear camera	\$	100.00	50
8	To transfer bootlid fittings	\$	150.00	80
Total Labour		\$	2,650.00	
Grand Total		\$	9,136.63	

GST Will be reflected in the final bills

NOTE : -

PLEASE INFORM US WITHIN 14 DAYS, FROM THE DATE OF THIS LETTER, IN THE EVENT THAT THE OWNER/DRIVER IS IN BREACH OF ITS POLICY WITH YOUR COMPANY, FAILING WHICH WE SHALL HOLD YOUR COMPANY LIABLE FOR ALL COSTS OF REPAIRS, LOSS OF USE AND STORAGE.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Total: 4198.75

L/S: 3350

04 Days