

TO :

ESTIMATE REPORT

1ST Quotation

FAX NO:

11/09/2024 11:44

JOB-NO: 50116363

Page 1 of 2

OWNER'S PARTICULARS

NAME: CityCab PTE LTD (Fleet)

CONTACT: 65533880

ADDRESS: 383 SIN MING DRIVE
SINGAPORE 575717 0

64739522

VEHICLE DETAILS

LICENSE NO: SHD8596D

TRANS: AUTO

CHASSIS: KMHLB41UMGU093835

MAKE / MODEL: HYUNDAI / i40

ENGINE: D4FDHU731303

OWNER'S INSURER: MS First Capital Insurance Limited

JOB-CODE: TP

SA: Ding Auto User 1

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
-------------	-----	--------------	----------	------------	-----	----------	-----------

LABOUR

1 STRAIGHT AND PANEL BEAT ACCIDENT AREA	1.00	700.00	0.00	700.00		Y	400
2 SUNDRIES	1.00	50.00	0.00	50.00		Y	20
3 RUST PROOFING	1.00	80.00	0.00	80.00		Y	40
4 DIAGNOSTIC(CLEAR FAULT CODE) & CHECK WIRING & LIGHTING SYSTEM	1.00	180.00	0.00	180.00		Y	80
5 R&R RADIATOR & CONDENSOR & TURBO INTERCOOLER	1.00	150.00	0.00	150.00	940	Y	X11
6 VACUUM & TOP UP AIR COND GAS R-134A	1.00	120.00	0.00	120.00		Y	X11
7 RESPRAY FRONT BUMPER	1.00	250.00	0.00	250.00		Y	200
8 RESPRAY FRONT FENDER RH	1.00	250.00	0.00	250.00		Y	200
TOTAL:		1,780.00	0.00	1,780.00			

MATERIALS

1 FRONT BUMPER <i>de</i>	1.00	599.68	119.94	479.74	L	1007.38	Y
2 FRONT BUMPER RETAINER RH <i>?</i>	1.00	48.32	9.66	38.66	L		Y
3 FRONT FENDER RH <i>sm</i>	1.00	659.50	131.90	527.60	L		Y
4 FRONT SUPPORT PANEL <i>X</i>	1.00	962.87	192.57	770.30	L		Y
5 FRONT BUMPER CLIP SET <i>m</i>	1.00	45.00	0.00	45.00	S	30	Y
6 RADIATOR COOLANT <i>X</i>	1.00	60.00	0.00	60.00	S		Y
TOTAL:		2,375.37	454.07	1,921.30			

TOTAL PARTS & LABOUR :	4,155.37	454.07	3,701.30
------------------------	----------	--------	----------

EXCESS/LOADING:\$ 0.00

No. Of Day:

*4 days*RE-SURVEY: BEFORE AFTER PAINTING

PART-BY-PART OF LUMP SUM: \$

DATE OF SURVEY: *16 / 09 / 24*

SURVEYED BY:

Rasul

CONTACT NO:

90010068

FAX NO:

NOTE: LUMP SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED
60190078

Ding Auto User 1

HS - \$1,600 / 4 days