



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LIBERTY INSURANCE PTE LTD ONE RAFFLES QUAY #25-01 NORTH TOWERSINGAPORE 048583 ATTN: ANDY SEAH			Ref: CS/LIP24090220/Rqh3m4(N) Date: 02/04/2025 Code: LIP	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	XE 8303M	Veh. Inspected	FBV 7774P	
Policy No.	SD23V05143/VCH/R00	Coverage (\$)	0.00	
Claim No.	AVS24/2801	Excess (\$)	0.00	
Assign From	ANDY SEAH	Assign Date	12/09/2024	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	YAMAHA XSR155 MANUAL	c.c	155	
Engine No.	HIDDEN	Year of Reg.	2023	
Chassis No.	MH3RG4760NK047589	Colour	BLUE	
Odometer	23503 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	110/70-17	PIRELLI	4 mm	
L/H Front Tyre			mm	
R/H Rear Tyre	140/70-17	PIRELLI	5 mm	
L/H Rear Tyre			mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	09/09/2024	Inspection Date	16/09/2024	
Survey held at	AHFOOKMOTOR.COM LLP 5 SOON LEE STREET #01-15 PIONEER POINT SINGAPORE 627607			
<b>5a. Remarks</b>				
A)REGISTRATION DATE: 04 DEC 2023 B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			3 Working Days	