



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS LIBERTY INSURANCE PTE LTD	Ref:	CS/LIP24090221/Unh3
ONE RAFFLES QUAY #25-01 NORTH TOWER	Date:	23/09/2024
SINGAPORE 048583	Code:	LIP

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBM 3320P	Veh. Inspected	SMU 871M
Policy No.	-	Coverage	0
Claim No.	AVS24/2779	Excess	\$0.00
Assign From	ANDY SEAH	Assign Date	12/09/2024

2. Vehicle Details

Make & Model	B.M.W. 216I (A)	C.C	1499
Engine No.	35045964B38A15A	Year of Reg.	29/07/2020
Chassis No.	WBA6V120805R33613	Colour	BLUE
Odometer	71309 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	215/55R17	MICHELIN	7
L/H Front Tyre	215/55R17	MICHELIN	7
R/H Rear Tyre	215/55R17	MICHELIN	7
L/H Rear Tyre	215/55R17	MICHELIN	7

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	06/09/2024	Inspection Date	13/09/2024
Survey held at	JEMENTAH MOTOR WORKS BLK 14 DEFU LANE 10 #01-406 SINGAPORE 539195		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days