

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SMV 871M

at Workshop m/s Jemutoh

of _____

Insured: GAM3320P

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: **The veh had commenced its repair at the time of inspection.**

N/S	O/S

Bal. or Market Value: 100k.

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

26d

Date: _____ Person Contacted: 27A 4742

Vehicle: IN / OUT

Veh No: SMU 871M Yr Regn: 29/07/20

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CA

Make: BMW 216i c.c. 1499

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: 71309 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WBA6V120 for R33613

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/55-17

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front 7 mm Rear 7 mm

R/Bal. _____ mm R/Bal. _____ mm

L/Bal. 7 mm L/Bal. 7 mm

D.O.A. 06/09/24 D.O.I. 13/9/24

Survey held at _____

Des. of Damages: Rear / Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time	Action / Instruction
<u>23/9/24</u>	<u>1/s \$4300 inform AH Yang</u>
	<u>(Red. \$8698.21, 66%)</u>

Date/Time, File Pass to? : Preli. Report : Final Report

Days Of Repair: 4
Resurvey No. of Trip: _____

Survey Fee:	
Transportation:	
_____ S + RS, _____ SI	
Photos	
Others	
TOTAL	

Add Fee: : Site Insp (\$ _____) : Interview (\$ _____) : Tech. Invs (\$ _____) : Weekend (\$ _____)

Report Format : _____
Lump Sum / I.B.I.: (\$ _____)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	226D
Vehicle Details	
Vehicle No.:	SMU871M
Vehicle to be Exported:	No
Intended Deregistration Date:	13 Sep 2024
Vehicle Make:	B.M.W.
Vehicle Model:	216I GRAN TOURER
Primary Colour:	Blue
Manufacturing Year:	2020
Engine No.:	35045964B38A15A
Chassis No.:	WBA6V120805R33613
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$32,606.00
Original Registration Date:	29 Jul 2020
First Registration Date:	29 Jul 2020
Transfer Count:	0
Actual ARF Paid:	\$37,649.00 <i>18824</i>
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	28 Jul 2030
PARF Rebate Amount:	\$28,236.00
Intended COE Rebate Details	
COE Expiry Date:	28 Jul 2030
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$32,699.00
COE Rebate Amount:	\$19,206.00
Total Rebate Amount:	\$47,442.00
Message	
You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE.	

The information contained herein is correct as at 13 Sep 2024

OK

Home Used Cars Listing

All Category Filter Search

2020 X

20 Vehicles

Car Make	Car Model	Price Range	Depreciation	2020	Mileage
	BMW 2 Series 216i Gran Tourer	\$120,800 Instl. \$1,129 /mth	\$16,180 /yr 1 Owner	30-Dec-2020	59,000 km
1 owner, 5 years warranty & servicing at PML. Fully maintained by PML since day 1. Flexible loan packages available. Contact now for more details! Posted 12-Sep-2024 <input type="checkbox"/> Compare					
	BMW 2 Series 216i Gran Tourer	\$115,800 Instl. \$1,326 /mth	\$16,280 /yr 1 Owner	27-Aug-2020	60,000 km
1 Owner Unit! Low Mileage Done! Fully Serviced by PML! 5 Years Agent Warranty From Date of Registration! Well Maintained 7 Seater MPV! Original Paintwork and Pristine Condition Inside Out! Road Tax till 26 Feb 2025! Trade In and 100% Immediate Loan Approval Available, Bank/In House Loan. Call Now to View this Beauty! Posted 12-Sep-2024 <input type="checkbox"/> Compare					
	BMW 2 Series 216i Active Tourer	\$91,300 Instl. \$1,147 /mth	\$13,890 /yr 3 Owners	17-Jan-2020	53,000 km
Drive away a BMW 216 and weave through urban traffic with ease. Super fuel efficient low mileage unit. Servicing just done. Wear and tear replaced. View to believe! Comes with 1 year engine/gearbox warranty for ultimate peace of mind. 3 foc servicing worth \$800 thrown in! Flexible loan options available! Consignment unit, viewing by appointment basis only. Don't miss! WhatsApp us today! Precision Automobile Pte Ltd Posted 12-Sep-2024 <input type="checkbox"/> Compare					

Compare

利民达摩多



*no. of Authorised
no
meras
13/5/20
1/5 4300
4 days
Zhang Mr. Anthony*

Jementah Motor Works

Blk 14 Defu Lane 10 #01-406
Singapore 539195
H/P : 9299 6636 Fax : 6285 7054

Date : 12-Sep-24

Estimated repair cost of SMU 871 M BMW 216i

<u>Qty</u>	<u>Description</u>		<u>Amt S(\$)</u>
	<u>List Items</u>		
1	Rear windscreen inner seal <i>neu</i>		\$ 95.00 ✓
1	Rear tailgate <i>D2/3014</i>	1574.60	\$ 1,850.00 ✓
2	Rear tailgate dampers <i>11</i>		\$ 707.80 X
1	Rear tailgate inner board <i>11</i>		\$ 381.25 X
2	Rear tailgate lamps <i>o/s scu</i>	212.25	\$ 511.30 <i>1pc</i>
1	Rear tailgate lock <i>11</i>		\$ 193.80 +
1	Rear tailgate logo <i>neu</i>		\$ 71.25 ✓
1	Rear tailgate rubber <i>11</i>		\$ 143.00 X
1	Rear tailgate "216i" emblem <i>neu</i>	60.00	\$ 88.00 ✓
2	Rear taillamps <i>o/s scu</i>	303.20	\$ 845.20 <i>1pc</i>
1	Rear end panel <i>n</i>		\$ 635.20 X
1	Rear end panel inner garnish <i>11</i>		\$ 179.15 X
1	Rear bumper <i>7011</i>	1132.40	\$ 1,245.45 ✓
1	Rear bumper inner frame garnish <i>oro</i>		\$ 122.70 ✓
1	Rear bumper lower diffuser <i>NZ</i>		\$ 471.00 X
2	Rear bumper reflectors <i>11</i>		\$ 77.40 X
1	Rear bumper reinforcement <i>D/S</i>		\$ 458.10 ✓
2	Rear bumper side retainers <i>11</i>		\$ 122.70 X
1	Rear tow hook cover <i>m/s</i>	28.00	\$ 65.00 ✓
2	Rear bumper PDC sensors <i>SVC</i>		\$ 497.40 X
1	Control module for park assistant kit <i>11</i>		\$ 526.10 X
1	Park assistant kit support bracket <i>CR</i>		\$ 185.00 ✓
			\$ 9,471.80
		Less 5%	\$ 473.59
			\$ 8,998.21

Special Nett Items

1	Rear windscreen sealant	<i>neu</i>	\$	80.00	<i>40</i>
1	Rear bumper clip (1 set)	<i>neu</i>	\$	60.00	<i>30</i>
			\$	<u>140.00</u>	

S/N

LABOUR CHARGES

1	To remove, replaced damaged lamps and check up rear wiring.		\$	80.00	<i>20</i>
2	To remove and refit inner garnishes.		\$	<i>17</i> 150.00	<i>X</i>
3	To remove and refit rear reverse sensor.		\$	120.00	<i>30</i>
4	To transfer rear tailgate mechanism and wiring assembly.		\$	80.00	<i>50</i>
5	To remove and refit rear windscreen glass.		\$	180.00	<i>120</i>
6	To apply undercoating.		\$	150.00	<i>30</i>
7	Panel beating.		\$	1,600.00	<i>440</i>
8	To re-spray painting on the affected areas.		\$	1,500.00	<i>600</i>
			\$	<u>3,860.00</u>	

Grand Total :

\$ 12,998.21

LKK Auto Consultants hence notify the Repairer of the following:

- To rectify before/after spray painting
- To display damaged parts, if necessary
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be rectified and is subject to final approval from Insurer's Company

Acknowledged by Repairer
 Signature:
 Date:

P-42425
52
-403038
70
1290

539038
202

4312