

SERVE YOU MOTOR PTE LTD

BLOCK 5033 ANG MO KIO INDUSTRIAL PARK 2
 #01-265, SINGAPORE 569536
 TEL. NO: 64810555 / FAX NO. 64831654
 E-MAIL: elainesyms@gmail.com

INS: Liberty ins
 COMPANY: A&S TRANSIT PTE. LTD
 Registration no. : PZ 1144 K / YUTONG ZK6107 HE AUTO
 DOA: 10-Sep-24
 Date : 13-Sep-24 Quotation No. : 11440910

S/N	Qty	Item	Amount
-----	-----	------	--------

LIST ITEMS

1	1	Rear bumper RH side corner panel	\$ <i>n</i> 1,650.00 <i>x</i>
2	1	Rear RH engine compartment cover with grille	\$ <i>n</i> 2,200.00 <i>x</i>
3	2	Rear RH engine compartment cover hydraulic stay	\$222 \$ <i>sm</i> 444.00 <i>x</i>
4	2	Rear RH engine compartment lower cover lock	\$ <i>n</i> 385.00 <i>x</i>
5	2	Rear RH engine compartment cover reflector lamp	\$188 \$ <i>sm</i> 376.00 <i>x</i>
6	1	Rear center RH compartment cover with grille	\$ <i>As</i> 1,855.00 ✓
7	1	Rear center RH compartment cover reflector lamp	\$ <i>cm</i> 75.00 ✓
8	1	Rear RH wheel arch panel	\$ <i>n</i> 1,850.00 <i>x</i>
9	1	Rear RH wheel mud flap	\$ <i>sm</i> 236.00 <i>x</i>
10	1	Rear diesel tank cover with lock	\$ <i>n</i> 258.00 <i>x</i>
			\$ 7,679.00
Less 10 %			\$ 767.90
			\$ 6,911.10

SPECIAL NETT ITEMS

1	1	Company logo art design for RH side portion	(Bill)	Acq \$	3,800.00	<i>2400</i>
				Sub-total:	\$ 3,800.00	

LABOUR CHARGE

1	To dismantle / renew the accident damaged portion. To panel beating, reshape, straighten, orientate and align repair / replacement parts.	\$1,800.00	<i>1000</i>
2	To disconnect and refix wiring, remove and refit rear RH fog light, rear RH lamp and reverse sensor to facilitate repair.	\$120.00	<i>200</i>
3	Supply spray paint material and necessary items to respray on accident damage area.	\$2,800.00	<i>1000</i>
Sub-total:		\$7,840.00	

Total Parts and Labour Cost of Repair \$18,551.10

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts price are subject to confirmation
- This quotation is on a "Without Prejudice" basis
- No general liability is allowed
- Damaged part(s) must be resurveyed and approved by Insurance Company

Not Authorised
 L1 Pump & 4900e
 Heavy After Paint
 5 days