

# SERVE YOU MOTOR PTE LTD

BLOCK 5033 ANG MO KIO INDUSTRIAL PARK 2  
 #01-265, SINGAPORE 569536  
 TEL. NO: 64810555 / FAX NO. 64831654  
 E-MAIL: elainesyms@gmail.com

INS: Liberty ins

COMPANY: A&S TRANSIT PTE. LTD

Registration no. : PZ 1144 K / YUTONG ZK6107 HE AUTO

DOA: 10-Sep-24

Date: 13-Sep-24

Quotation No. : 11440910

| S/N | Qty | Item | Amount |
|-----|-----|------|--------|
|-----|-----|------|--------|

### LIST ITEMS

|           |   |                                                 |                                    |
|-----------|---|-------------------------------------------------|------------------------------------|
| 1         | 1 | Rear bumper RH side corner panel                | \$ <i>n</i> 1,650.00 <i>x</i>      |
| 2         | 1 | Rear RH engine compartment cover with grille    | \$ <i>n</i> 2,200.00 <i>x</i>      |
| 3         | 2 | Rear RH engine compartment cover hydraulic stay | \$222 \$ <i>sn</i> 444.00 <i>x</i> |
| 4         | 2 | Rear RH engine compartment lower cover lock     | \$ <i>n</i> 385.00 <i>x</i>        |
| 5         | 2 | Rear RH engine compartment cover reflector lamp | \$188 \$ <i>sn</i> 376.00 <i>x</i> |
| 6         | 1 | Rear center RH compartment cover with grille    | \$ <i>sn</i> 1,855.00 ✓            |
| 7         | 1 | Rear center RH compartment cover reflector lamp | \$ <i>cm</i> 75.00 ✓               |
| 8         | 1 | Rear RH wheel arch panel                        | \$ <i>n</i> 1,850.00 <i>x</i>      |
| 9         | 1 | Rear RH wheel mud flap                          | \$ <i>sn</i> 236.00 <i>x</i>       |
| 10        | 1 | Rear diesel tank cover with lock                | \$ <i>n</i> 258.00 <i>x</i>        |
|           |   |                                                 | \$ 7,679.00                        |
| Less 10 % |   |                                                 | \$ 767.90                          |
|           |   |                                                 | \$ <b>6,911.10</b>                 |

### SPECIAL NETT ITEMS

|            |   |                                             |        |                    |             |
|------------|---|---------------------------------------------|--------|--------------------|-------------|
| 1          | 1 | Company logo art design for RH side portion | (Bill) | \$ 3,800.00        | <i>2400</i> |
| Sub-total: |   |                                             |        | \$ <b>3,800.00</b> |             |

### LABOUR CHARGE

|            |                                                                                                                                           |            |             |
|------------|-------------------------------------------------------------------------------------------------------------------------------------------|------------|-------------|
| 1          | To dismantle / renew the accident damaged portion. To panel beating, reshape, straighten, orientate and align repair / replacement parts. | \$1,800.00 | <i>1000</i> |
| 2          | To disconnect and refix wiring, remove and refit rear RH fog light, rear RH lamp and reverse sensor to facilitate repair.                 | \$120.00   | <i>200</i>  |
| 3          | Supply spray paint material and necessary items to respray on accident damage area.                                                       | \$2,800.00 | <i>1000</i> |
| Sub-total: |                                                                                                                                           | \$7,840.00 |             |

**Total Parts and Labour Cost of Repair \$18,551.10**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts price are subject to confirmation
- Third party claims on a "Without Prejudice" basis
- No claim for excess (DMS) is allowed
- Subsequent repairs must be resurveyed and
- Resurvey must be approved from Insurance Company

Repairer

Not withold  
 11 Sep & 4900  
 Heavy After Paint  
 5 days