

CHIA AUTO SERVICES PTE LTD

23 Kaki Bukit Avenue 4 #04-01 Vicom Inspection Centre Singapore 415933

Tel: 6243 1373 Fax: 6243 1376

Reg. No: 201538764H

Email: CA3SERVICES@GMAIL.COM

ATTENTION:	MOTOR CLAIMS DEPARTMENT
DATE:	18-09-24
CLAIM TYPE:	T/P CLAIM
TO:	INCOME
VEHICLE DETAILS	
VEHICLE NO:	SMS5538D
MAKE & MODEL:	HONDA JAZZ 1.3 CVT
CHASSIS NO:	
ACCIDENT DETAILS	
DATE:	7 September, 2024
TIME:	16:00HRS
THIRD PARTY REQUESTOR:	JACK LI

CLAIM DETAILS: PARTS

S/N:	DESCRIPTION	QTY:	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT BUMPER <i>Rehd</i>	1	\$ 780.00	\$ 780.00
2	FORNT BUMPER SIDE RETAINER <i>New</i>	1	\$ 60.00	\$ 60.00
3	FORNT BUMPER FOGLAMP COVER <i>cut</i>	1	\$ 120.00	\$ 120.00
4	HEADLAMP <i>New</i>	1	\$ 1,322.50	\$ 1,322.50
5	HEADLAMP LOWER BRACKET <i>New</i>	1	\$ 85.00	\$ 85.00
6	FRONT FENDER <i>Repair</i>	1	\$ 480.00	\$ 480.00

TOTAL PRICE \$ 2,847.50

LESS 20% \$ 569.50

SUB TOTAL PRICE \$ 2,278.00

SPECIAL NETT ITEMS

S/N:	DESCRIPTION	QTY:	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT BUMPER CLIPS(SET) <i>New</i>	1	\$ 20.00	\$ 20.00

TOTAL \$ 20.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)

1	PANEL BEATING, REMOVAL AND REPLACING PARTS	1	\$ 1,000.00	\$ 1,000.00
2	TO SPRAY PAINT AFFECTED AREA	1	\$ 1,000.00	\$ 1,000.00
3	TUFF COAT	1	\$ 200.00	\$ 200.00

4	WIRING CHECK	1	\$ 80.00	\$ 80.00
---	--------------	---	----------	----------

TOTAL \$ 2,280.00

660

ESTIMATE REPORT

TOTAL PARTS COST	\$	2,298.00
TOTAL LABOUR COST	\$	2,280.00
TOTAL REPAIR COST	\$	4,578.00

APPROVED DETAILS:

SURVEYOR:
 CONTACT NO.:
 PART BY PART/LUMP SUM
 NO. OF DAYS

Adrian King
 H/S 18/09/24

03 days

720
 + 20
 + 660

 1400
 -20% 280

 1120

Lump Sum \$ 1100 &
 3 days.