

FBW 610 U
Aerox V2

Towing — x 45 ✓

Towing to idar — x 45 - 90

Exc pip? Assy — Rx 495
Exc pwr cover — 85 ut ✓
Rear Manguag — ut 98

Rear Box Bracket — bt 185

GRAS
Rear Box — dis 80
Box bracket bt — 80
Labour — ~~1200~~ 350
500

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part during resurvey
- Parts prices are subject to insurance company
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company.

Acknowledged by Repairer
Signature: _____
Date: _____

Tanfik 97495749
16/9/24 2pm
Resy after repair
Tanfik 97495749
(2) 3 days

Parts 528
10% - 475.20
90
350
\$915.20
2 days
✱