

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CS/CT/24090228/4vh3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: SLD9809Gat Workshop m/s Belcon Air Tanjong

of _____

Insured: SNS 602RR

Policy No. _____


Claims No. **SNM24D205150**

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: **The veh had commenced its repair at the time of inspection.**Bal. or Market Value: \$40k.

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No**CA / REV / REP. / 24 HRS**Vehicle: INS / OUTDate: _____ Person Contacted: 274624583Veh No: SLD9809G Yr Regn: 26/07/16Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or CAMake: Toyota harris C.C. 1986Colour: Silver A/C: Insured / Std / NI / NASp. Reading: 116409 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: RSU 60008056Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 225/65-17

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /**TOYO / YOKO or**Front 6 mm Rear 6 mmR/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 07/09/24 D.O.I. 16/09/24

Survey held at _____

Des. of Damages: Frnt / Rear / O/S / N/S / U/C / Rooftop orN/S Rpt.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction Dep 15k.

30/9/24 7p video shown OI driver mirror fold inward already
 1/5 \$5000 in hand To share (red 10,019.50, 66%)

Date/Time, File Pass to?

☐ : Preli. ReportDays Of Repair: 3

1)

☐ : Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

S + RS, SI

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$) _____)

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Singapore NRIC
Owner ID:	955G

Vehicle Details

Vehicle No.:	SLD9909G
Vehicle to be Exported:	No
Intended Deregistration Date:	16 Sep 2024
Vehicle Make:	TOYOTA
Vehicle Model:	HARRIER 2.0 ELEGANCE AT ABS D/AIRBAG 2WD
Primary Colour:	Silver
Manufacturing Year:	2016
Engine No.:	3ZRB803204
Chassis No.:	ZSU600080856
Maximum Power Output:	111.0 kW (148 bhp)
Open Market Value:	\$27,703.00
Original Registration Date:	26 Jul 2016
First Registration Date:	26 Jul 2016
Transfer Count:	1
Actual ARF Paid:	\$25,785.00 12892

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	25 Jul 2026
PARF Rebate Amount:	\$14,181.00

Intended COE Rebate Details

COE Expiry Date:	25 Jul 2026
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$56,002.00
COE Rebate Amount:	\$10,402.00
Total Rebate Amount:	\$24,583.00

Message

You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE.

The information contained herein is correct as at 16 Sep 2024

OK



Home Used Cars Listing

All Category



Search

Save Search



2016 X

45 Vehicles

Car Make

Car Model

Price Range

Depreciation

2016

Mileage

Toyota Harrier 2.0A Premium
Panoramic Roof

\$43,800

Instl. \$1,523

/mth

\$15,440 /yr

27-Jul-2016

(1yr 10mths COE left)

150,000 km 2 Owners

Warranty

Posted 16-Sep-2024

Compare

Toyota Harrier 2.0A Premium
Panoramic Roof

\$46,888

Instl. \$1,709

/mth

\$17,460 /yr

07-Jul-2016

(1yr 9mths COE left)

5 Owners

Just arrived, most popular SUV with full bodykit. Well maintained, \$0 drive away, loan guaranteed approved. All bad credit and ex-bankruptcy welcome. High trade-in view to believe. Act fast, call now for more information

Posted 15-Sep-2024

Compare

Toyota Harrier 2.0A Premium
Panoramic Roof

\$39,888

Instl. \$1,609

/mth

\$15,180 /yr

21-Apr-2016


(1yr 7mths COE left)

3 Owners

Quick sale, very well maintain, accident free. Tip top driving condition. Excellent engine, gear box & body work. Must view no low baller. Best deal assure. Call now

Posted 14-Sep-2024

Compare

Toyota Harrier 2.0A Premium
Panoramic Roof

\$52,800

Instl. \$1,683

/mth

\$16,620 /yr

13-Oct-2016

(2yrs COE left)

2 Owners

Cheapest In The Market! Immediate Transfer Of Ownership Upon Collection! Trustworthy And Transparent Deals Backed By Positive Reviews! Positive After Sales Experience. 2 Owners Sporty Pearl White Unit, Premium Panoramic Model Fully Stock. Low Genuine Mileage! Extremely Well Maintained Unit With No Repairs Needed! Contact Us Now To View!

BuySafe

Skyline Auto Pte Ltd | Posted 14-Sep-2024

Compare

FALCON AIR AUTO SERVICES PTE LTD

Tel No. :

CHINA TAIPING INSURANCE (S) PTE LTD
3 ANSON ROAD
#16-00 SPRINGLEAF TOWER S(079909)

Attention : Motor Claim Department

Contact : 63896111 Fax No. : 62221033

Estimate : ES709625

Date : 16/09/2024

Vehicle Num. : SLD 9909G

Make/Model : TOYOTA HARRIER

Chassis/Eng# :

Accident Date : 16/09/2024

Claim No. :

Reference :

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LIST ITEMS :				
1.	1 PC	N/S HEADLAMP	6406.20	10,178.00 ✓
2.	1 PC	N/S HEADLAMP LOWER BRACKET		185.00 X
3.	1 PC	FRONT BUMPER		1,161.00 X
4.	1 PC	N/S FRONT BUMPER SIDE RETAINER		186.00 X
5.	1 PC	N/S FRONT FENDER	1121.00	1,981.00 ✓
6.	1 PC	N/S FRONT FENDER INNER SHIELD		757.00 X
7.	1 PC	N/S WING MIRROR		1,110.00 X
8.	1 PC	N/S FRONT DOOR GLASS		1,286.00 X
9.	1 PC	N/S FRONT DOOR GLASS MOULDING - OUTER		281.00 X
10.	1 PC	N/S FRONT DOOR CHROME MOULDING		381.00 X

List TotalS\$:

25.00% Discount S\$:

17,506.00

4,376.50

13,129.50

SPECIAL NETT ITEMS :				
1.	1 PC	FRONT BUMPER CLIP		40.00 X
2.	1 PC	FRONT BUMPER RIVET		60.00 X
3.	1 PC	N/S FRONT FENDER INNER SHIELD CLIP		40.00 X

Special Nett Total S\$:

140.00

CONTINUE / ...

FALCON AIR AUTO SERVICES PTE LTD

Tel No. :

CHINA TAIPING INSURANCE (S) PTE LTD
3 ANSON ROAD
#16-00 SPRINGLEAF TOWER S(079909)

Attention : Motor Claim Department

Contact : 63896111 Fax No. : 62221033

Estimate : ES709625

Date : 16/09/2024
Vehicle Num. : SLD 9909G
Make/Model : TOYOTA HARRIER
Chassis/Eng# :
Accident Date : 16/09/2024
Claim No. :
Reference :
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LABOUR :
TO FOCUS HEADLAMP & WIRING
TO RUST PROOF PANELS
TO REPAIR INNER PANEL, ACCIDENT DAMAGE AREA, REPLACEMENT
OF PARTS AND ALIGN THE SAME
TO PUTTY AND SPRAY PAINT ON ACCIDENT DAMAGE AREA

50.00 20
150.00 30
750.00 250
800.00 400

1,750.00

Labour Total S\$:

E. & O.E.

Total S\$: 15,019.50

for FALCON AIR AUTO SERVICES PTE LTD

TAMPINES BRANCH

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts for resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

p- 7527.2
252
5645.40

700
6345.40
211
5036