

ACCORD AUTO SERVICES PTE LTD

10 Ang Mo Kio Industrial Park 2A

#03-11 AMK Autopoint Singapore 568047

Tel: 6481 9518 / 6481 9517 Fax: 6481 9516 email: claims@mycarworkshop.com.sg

Not Authority ESTIMATE

3RD PARTY

MSIG Insurance (Singapore) Pte Ltd
ATTN: ACCIDENT CLAIMS DEPARTMENT

FIRST REGISTRATION: 14.06.2017

61 Rm 811, 350/h

DATE :

VEHICLE NO :

VEH MAKE/MODEL :

YOM :

CHASSIS NO :

DATE OF ACCIDENT :

12.09.2024

SLP6675L

TOYOTA ALTIS

2016

MR053REH104563030

5 days

NO	QTY	DESCRIPTION	AMOUNT \$
		<u>LIST PRICE:-</u>	
1	1	FRONT BONNET <i>1418.40</i>	\$ <i>R1</i> 1,743.90 ✓
2	1	FRONT BONNET HINGES LH & RH	\$ <i>R2</i> 163.60 X
3	1	FRONT HEADLAMP LH <i>3243.20</i>	\$ <i>CM</i> 4,617.90 ✓
4	1	FRONT HEADLAMP BRACKET LH	\$ <i>CM</i> 905.40 ✓
5	1	FRONT BUMPER <i>589.60</i>	\$ <i>CM</i> 130.80 ✓
6	1	FRONT BUMPER SIDE RETAINER LH	\$ <i>mf CM</i> 473.20 ✓
7	1	FRONT FOG LAMP LH <i>315</i>	\$ <i>SL</i> 171.60 X
8	1	FRONT FOG LAMP GARNISH LH	\$ <i>CM</i> 1,582.40 ✓
9	1	AIR BOX ASSY <i>R1 195</i>	\$ <i>R1</i> 1,386.90 ✓
10	1	FRONT FENDER LH <i>761.45</i>	\$ <i>R1</i> 381.30 ✓
11	1	FRONT FENDER INNER SHIELD LH <i>226.60</i>	\$ <i>R1</i> 676.30 ✓
12	1	FRONT SHOCK ABSORBER LH	\$ <i>SL</i> 230.00 ✓
13	1	FRONT SHOCK ABSORBER SPRING LH	\$ <i>SL</i> 303.30 ✓
14	1	FRONT SHOCK ABSORBER MOUNTING KH	\$ <i>SL</i> 46.50 ✓
15	1	FRONT SHOCK ABSORBER DUST COVER LH	\$ <i>R1/SL</i> 2,732.00 ✓
16	1	STEERING RACK	\$ <i>R1</i> 1,663.70 ✓
17	1	FRONT DRIVE SHAFT LH	\$ <i>R1</i> 878.60 ✓
18	1	FRONT KUNCKLE ARM LH <i>585</i>	\$ <i>SL</i> 100.80 ✓
19	1	FRONT WHEEL BEARING LH	\$ <i>R1</i> 362.50 ✓
20	1	FRONT WHEEL BEARING HUB LH	\$ <i>SL</i> 582.20 ✓
21	1	FRONT ANTI ROLL BAR LH	\$ <i>SL</i> 328.00 ✓
22	1	FRONT ANTI ROLL BAR LINKAGE LH	\$ <i>Dis</i> 1,113.90 ✓
23	1	FRONT LOWER ARM LH <i>543.90</i>	\$ <i>SL</i> 2,803.60 X
24	1	FRONT CROSSMEMBER	\$ <i>PD</i> 3,032.10 ✓
25	1	RIM <i>P1 2512.80</i>	
26			
27			
28			
TOTAL - LIST ITEM			\$ 26,410.50
LIST PRICE:-			\$ 6,602.63
TOTAL			\$ 19,807.88

