

724C

**TOTAL**

Z BP-GRA  
TP VE  
TOW  
DAT  
NC  
B  
B  
L  
B  
F



Mercedes-Benz

Cycle & Carriage  
Industries Pte Limited  
Authorised Dealer  
Company No. 196400367W  
GST Reg No. MR-8500111-X

## ESTIMATE FOR SKZ1550E

MSIG INSURANCE (S'PORE) PTE LTD

MOTOR CLAIM DEPARTMENT  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807  
68277888

Vehicle & Document Information  
WIP No 20788  
Reg No/Reg Date SKZ1550E / 04/01/2016  
Date In/Mileage / 0  
Chassis No WDD2050422R122169  
Engine No 27492030478461  
Make/Model MB/MB C 200 SEDAN (W205) "AVANTGARDE / A  
Colour/Trim 027 799 Diamond Whi/ 042 201 Black

Account No	Terms	Date/Time Printed	CSE	Operator
WI000558	Credit	13/09/2024/ 16:05	CH	371 / Go Chee Han

Description of Goods / Services

Qty Unit Price Disc% Amount

Z REQUEST

Customer Request

M BPNSUN

POLICY NO/ACC DATE : B300915912QMY // 11-9-2024

TOW IN/EXCESS : 11-9-2024 // TBA

DATE IN/DATE SURVEY:

BY/AUTHORIZED ON :

A BPILAB

TO REMOVE & INSTALL AFFECTED BODY PANEL FOR REPAIRS

A BPIRES

RESPRAY ENGINE HOOD

A BPILAB

USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD. NETT

A BPILAB

EXTRACT REFRIGERANT, CHECK FOR LEAKS, REFILL (WHEN WORKING ON AIR CONDITIONING)

A BPILAB

FRAME FLOOR WIRING HARNESS REPLACE WITH REMOVE/INSTALL EVAPORATOR UNIT INSTRUMENT PANEL & HEADLINE & STEERING COLUMN & AIRBAG & FUSE BOX DETACHABLE PARTS IN AREA TO BE REPAIRED.

A BPILAB

TO WASH FIRE EXTINGUISHER POWDER.

A BPILAB

TO DROP AND REFIT / RENEW 'ABR' PUMP AND CONTROL UNIT, TO BLEED AND RESET 'ESP' SYSTEM.

A 97250001

CAVITY PRESERVATION ON REPLACED OR REPAIRED BODY PANELS PERFORM

M BATTERY SENSOR

M INSULATING CAP

M INSULATING CAP

M CURRENT LIMITER

M EQUIPMENT COMPARTMENT

1.00	448.90	00.00	448.90
1.00	9.33	00.00	9.33
1.00	9.33	00.00	9.33
1.00	441.74	00.00	441.74
1.00	120.75	00.00	120.75

Confirmed & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



and Mercedes-Benz are trademarks of Mercedes-Benz Group AG

Pandan Loop Service Center  
188 Pandan Loop  
Singapore 128378  
Tel: 6777 8388  
Fax: 6779 5383  
www.mercedes-benz.com.sg





Mercedes-Benz

Cycle & Carriage  
Industries Pte Limited  
Authorised Dealer  
Company No. 196400367W  
GST Reg No. MR-8500111-X

## ESTIMATE FOR SKZ1550E

MSIG INSURANCE (S'PORE) PTE LTD

MOTOR CLAIM DEPARTMENT  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807  
68277888

## Vehicle &amp; Document Information

WIP No 20788  
Reg No/Reg Date SKZ1550E / 04/01/2016  
Date In/Mileage / 0  
Chassis No WDD2050422R122169  
Engine No 27492030478461  
Make/Model MB/MB C 200 SEDAN (W205) "AVANTGARDE" / A  
Colour/Trim 027 799 Diamond Whi/ 042 201 Black

Account No	Terms	Date/Time Printed	CSE	Operator
WI000558	Credit	13/09/2024/ 16:05	CH	371 / Go Chee Han

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M RH/FRONT RELAY UNIT	1.00	591.71	00.00	591.71
M FUSE CARRIER	1.00	6.31	00.00	6.31
M COVER, EQP. COMPARTMENT	1.00	49.13	00.00	49.13
M INFO SHT. RELAYS + FUSES	1.00	8.61	00.00	8.61
M ENGINE ELECTRICAL WIRING HARNESS	1.00	2611.73	00.00	2611.73
M FUSE BOX ELECTRICAL WIRING HARNESS	1.00	168.72	00.00	168.72
M MAIN ELECTRICAL WIRING HARNESS	1.00	5749.95	00.00	5749.95
M RIGHT WHEEL HOUSE PARTITION	1.00	137.87	00.00	137.87
M CTR/FIREWALL PARTITION	1.00	190.74	00.00	190.74
M DAMPENING, FIREWALL	1.00	196.05	00.00	196.05
M RIGHT WATER BAFFLE	1.00	263.40	00.00	263.40
M RIGHT SIDE SEAL, AIR DUCT	1.00	14.89	00.00	14.89
M SEALING, AIR DUCT	1.00	56.04	00.00	56.04
M EXPANSION RIVET	2.00	3.33	00.00	6.66
M FEED-THROUGH GROMMET	1.00	2.92	00.00	2.92
M RIGHT DRAIN VALVE	1.00	58.65	00.00	58.65
M LEFT WATER BAFFLE	1.00	314.54	00.00	314.54

Rasul  
Hp 9001068

18 clump

13/09/24

EXCESS: TRA

Revert

Rey after repair  
P/P

**LKK Auto Consultants** hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Confirmed &amp; accepted by

Nett 34,597.97  
9% GST on 34597.97 3113.82

Total Payable 37,711.79

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.  
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center  
188 Pandan Loop  
Singapore 128378  
Tel: 6777 8388  
Fax: 6779 5383  
www.mercedes-benz.com.sg



and Mercedes-Benz are trademarks of Mercedes-Benz Group AG

[> Back to OneMotoring](#)

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	724C
Vehicle Details	
Vehicle No.:	SKZ1550E
Vehicle to be Exported:	No
Intended Deregistration Date:	15 Sep 2024
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	C200 AVANTGARDE (R17 LED)
Primary Colour:	White
Manufacturing Year:	2015
Engine No.:	27492030478461
Chassis No.:	WDD2050422R122169
Maximum Power Output:	135.0 kW (181 bhp)
Open Market Value:	\$40,985.00
Original Registration Date:	04 Jan 2016
First Registration Date:	04 Jan 2016
Transfer Count:	1
Actual ARF Paid:	\$44,379.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	03 Jan 2026
PARF Rebate Amount:	\$24,408.00
Intended COE Rebate Details	
COE Expiry Date:	03 Jan 2026
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$60,001.00
COE Rebate Amount:	\$7,806.00
<b>Total Rebate Amount:</b>	<b>\$32,214.00</b>
Message	
You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE.	

The information contained herein is correct as at 15 Sep 2024

OK



# Mercedes-Benz C-Class C200 Avantgarde

**\$48,800** Instalment \$2,511/mth

💰 Apply for 2.48% loan

♡ Shortlist

✔ Get Warranty

**NEW CAR DISCOUNTS & OFFERS**  
BEST DEAL DAILY!

▶ VIEW ALL  
PROMO

Overview Financial Photo Research

Depreciation	📘 \$20,860 / year
Reg. Date	07-Jan-2016 (1yr 3mths 22days COE left)
Manufactured	📘 2015
Mileage	110,000 km (12.6k / year)
Transmission	Auto
Engine Cap	1,991 cc
Road Tax	📘 \$1,202 / year
Power	135.0 kW (181 bhp) View specs of the <a href="#">Mercedes-Benz C-Class Saloon (2014-2018)</a>
Curb Weight	📘 1,465 kg
COE	📘 \$61,103
OMV	📘 \$39,977
ARF	📘 \$42,968