

(08/11/13) wef

ASS. REC. BY:

REF: CS/FCI 24090240/Rvp3

9
035w

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SM25629M
at Workshop m/s KPH MOTOR
of 255, ALEXANDRA RD
Insured: FCI

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Sal. or Market Value:

157K

IDAC Accident Report:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No: SM25629M Yr Regn: 2021 MAY
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or

Make: HONDA 004864 24 EX-S C.C. 2356

Colour: GREEN A/C: Insured / Std / NI / NA

Sp. Reading: 044926 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: JHMRC 1880MC 200727

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F:

R:

215/60R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO, or

Front

Rear

R/Bal. 6 mm

R/Bal. 6 mm

L/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 11/09/24

D.O.I. 14/10/24

Survey held at

ALEXANDRA RD

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

N/S REAR

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

REPAIR LUMG - 99K

Date/Time, File Pass to?

☐
☐

Prel. Report

Final Report

1) Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee: ☐ Site Insp (\$

☐ Interview (\$

☐ Tech. Invs (\$

☐ Weekend (\$

) \$ + RS \$

) Photos

) Others

Report Format:

Lump Sum / I.B.I. (\$

TOTAL



KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer : MS FIRST CAPITAL INSURANCE LIMITED
#42-0116 RAFFLES QUAY
HONG LEONG BUILDING
SINGAPORE 048581
Registration No : SMZ5629M
Chassis No : JHMRC1880MC200727
Model : ODYSSEY 2.4 EX-S 21YM (EURO 6)
Owner's Name : LEE SEONG HEE
Ins Policy No. :
Date of Accident : 11/9/2024

Document No. : SQT24002489
Date : 13. Sep 2024
Customer No. : WZF002
Svc Advisor : NG SIN HAI
Engine No : K24W72540157
Date | Time : 13. Sep 2024 1:49:46 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Page 1

Item	Description	Qty	Unit Price	Disc %	Amount	9% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER: OWNER INSURER: ACC DATE: SURVEYED BY: DATE: REF NO: TP INSURER: TP VEH:						
04715-T6A-Z00ZZ	FACE,RR.BUMPER <i>Sur</i>	1	573.50	25	430.12	38.71	468.83
33555-SLJ-013	REFLECTOR ASSYL.RR. <i>?</i>	1	49.50	25	37.12	3.34	40.46
71560-T6A-Z01	MOULDING ASSY,L.RR.BUMPER SIDE <i>?</i>	1	191.80	25	143.85	12.95	156.80
71593-T6A-Z01	SPACER,R.RR.BUMPER SIDE <i>m</i>	1	20.90	25	15.67	1.41	17.08
71598-T6A-Z01	SPACER,L.RR.BUMPER SIDE <i>m</i>	1	20.90	25	15.67	1.41	17.08
91505-TM8-003	CLIP,BUMPER <i>m</i>	1	2.30	25	1.72	0.15	1.87
66100-T6A-Q50ZZ	PANEL COMP,REAR <i>?</i>	1	531.80	25	398.85	35.90	434.75
74940-TR0-003	BUZZER ASSYSMART <i>?</i>	1	65.60	25	49.20	4.43	53.63
84665-T6A-N23ZD	LINING COMP,L.RR.SIDE <i>?</i>	1	725.80	25	544.35	48.99	593.34
38387-TZ5-A01	ANTENNA ASSYL.F. <i>?</i>	1	64.70	25	48.52	4.37	52.89
NMFRS-8P-RS886	FRONT REAR SENSOR 8P <i>?</i>	1	465.00		465.00	41.85	506.85
BO-WS-SEALANT	WINDSCREEN SEALANT (N) <i>X</i>	2	60.00		120.00	10.80	130.80
Sum Item					2270.07	204.31	2,474.38
BOSUN	SUNDRIES	1	110.00		<i>30</i> 110.00	9.90	119.90
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	250.00		<i>180</i> 250.00	22.50	272.50
BOJSE	BODY JOINT SEALANT REAR END PANEL	1	120.00		<i>?</i> 120.00	10.80	130.80
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	250.00		<i>X</i> 250.00	22.50	272.50

Printed on 13/9/2024 1:55:15 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

Charges of \$50.00 (excluding GST) will be applicable for the request of quotation above \$2000.00

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

All quotations and prices are subjected to GST adjustment from 8% to 9% with effect from 1st Jan 2024.



KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)
Service and Body Repair
Tel: +65 6841 3838 Website: www.honda.com.sg
For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer : MS FIRST CAPITAL INSURANCE LIMITED
#42-0116 RAFFLES QUAY
HONG LEONG BUILDING
SINGAPORE 048581
Registration No : SMZ5629M
Chassis No : JHMRC1880MC200727
Model : ODYSSEY 2.4 EX-S 21YM (EURO 6)
Owner's Name : LEE SEONG HEE
Ins Policy No. :
Date of Accident : 11/9/2024

Document No. : SQT24002489 **Page** 2
Date : 13. Sep 2024
Customer No. : WZF002
Svc Advisor : NG SIN HAI
Engine No : K24W72540157
Date | Time : 13. Sep 2024 1:49:46 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	9% GST Amount	Amount incld GST
BKRP02M	CUT OFF & RENEW RR PANEL. STRAIGHTEN ALIGN	1	2000.00	650	2000.00	180.00	2180.00
BP06R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)	1	2000.00	520	2000.00	180.00	2180.00
BC011R	REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA	1	650.00	X	650.00	58.50	708.50
BC012R	RESET VEHICLE SMART ENTRY SYSTEM	1	650.00	X	650.00	58.50	708.50
BC011R	REMOVE INSTALL & CALIBRATE REAR AUTO TAILGATE	1	650.00	X	650.00	58.50	708.50
BC03R	TO PERFORM AIMING ON MULTI PURPOSE CAMERA FOR	1	650.00	X	650.00	58.50	708.50
Sum Labor					7330.00	659.70	7,989.70

Survey By
Date & Time
Excess
Status
Signature

Page - 1 of 9
14/10/24
3 days
By 64 print

Total Amount 9,600.07 864.01 10,464.08
Total (Inclusive of GST) 10,464.08

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Printed on 13/9/2024 1:55:15 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

Charges of \$50.00 (excluding GST) will be applicable for the request of quotation above \$2000.00

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

All quotations and prices are subjected to GST adjustment from 8% to 9% with effect from 1st Jan 2024.

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Foreign Identification Number
Owner ID:	035W
Vehicle Details	
Vehicle No.:	SMZ5629M
Vehicle to be Exported:	No
Intended Deregistration Date:	15 Oct 2024
Vehicle Make:	HONDA
Vehicle Model:	ODYSSEY 2.4 EX-S CVT
Primary Colour:	Silver
Manufacturing Year:	2021
Engine No.:	K24W72540157
Chassis No.:	JHMRC1880MC200727
Maximum Power Output:	129.0 kW (172 bhp)
Open Market Value:	\$31,225.00
Original Registration Date:	03 May 2021
First Registration Date:	03 May 2021
Transfer Count:	0
Actual ARF Paid:	\$35,715.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	02 May 2031
PARF Rebate Amount:	\$26,786.00
Intended COE Rebate Details	
COE Expiry Date:	02 May 2031
COE Category:	E - Open - all except motorcycle
COE Period(Years):	10
QP Paid:	\$47,806.00
COE Rebate Amount:	\$30,771.00
Total Rebate Amount:	\$57,557.00
Message	
You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE.	

The information contained herein is correct as at 15 Oct 2024

OK



Honda Odyssey 2.4A EX-S

\$156,800 Instalment \$1,432/mth

PREMIUM AD

💰 Apply for 2.48% loan

🛡️ BuySafe

♡ Shortlist



Overview Financial Photo Research

Depreciation	📘 \$21,430 / year
Reg. Date	08-Apr-2021 (6yrs 5mths 23days COE left)
Manufactured	📘 2021
Mileage	45,000 km (12.8k / year)
Transmission	Auto
Engine Cap	2,356 cc
Road Tax	📘 \$1,630 / year
Power	129.0 kW (172 bhp) View specs of the Honda Odyssey (2014-2021)
Curb Weight	📘 1,798 kg
COE	📘 \$47,001
OMV	📘 \$31,318

View car via BuySafe