

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Affiliated to Federation Internation	ale Des Experts En	Automobile	
MS	I IREDTV INISI IDAN		Ref:	CS/LIP24090254/Kvh3m4	
IVIO	LIBERTY INSURANCE PTE LTD ONE RAFFLES QUAY #25-01 NORTH TOWER				
	SINGAPORE 04858		Date:	29/11/2024	
			Code:	LIP	
1.		Policy Particulars :- THIRD PARTY CLAIM			
	Insured Veh.	SMM 9322P	Veh. Inspected	VLB 3338	
	Policy No.	-	Coverage	0	
	Claim No.	IVS24/1742	Excess	\$0.00	
	Assign From	ANDY SEAH	Assign Date	13/09/2024	
2. Vehicle Details					
	Make & Model	PROTON X90 (A)	C.C	1477	
	Engine No.	3G15TDP6PA6401441	Year of Reg.	18/07/2023	
	Chassis No.	PL1ZU2RVRQG003336	Colour	WHITE	
	Odometer	725 KM	Steering	IN ORDER	
	Brakes	IN ORDER	General	GOOD	
	Modification(s)	RIMS: STANDARD ALLOY RIM			
3. Conditions of Tyres					
		Size	Make	Balance (mm)	
	R/H Front Tyre	235/50R19	CONTINENTAL	9	
	L/H Front Tyre	235/50R19	CONTINENTAL	9	
	R/H Rear Tyre	235/50R19	CONTINENTAL	9	
	L/H Rear Tyre	235/50R19	CONTINENTAL	9	
4. Description of Damages					
THE	VEHICLE SUSTAIN	ED DAMAGES AT THE N/S BODY.			
DAM	AGES SEE DETAIL	S.			
5.	General Information				
	Accident Date	10/09/2024	Inspection Date	19/09/2024	
	Survey held at	THIAM HENG HUAT PTE LTD 176 SIN MING DRIVE #05-14 SINGAPORE 575721			
5a.	5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b. Estimate Days of Repair					
JD.					